

Nestor

July 22

Cuttery divider

Lot 32 CABINET QC

Done for BS40

Cut on site
June 30 if needed

MSR ENSUITE

NOTE CABINETS COVERED W/ PLASTIC
BUMPER RECD @ BOTH DOOR @ LEFT SINK
BUMPER MISSING @ LEFT DOOR @ RIGHT SINK
ADJUST DOORS & DRAWERS

DONE

MAIN BATH

FAR LEFT DOOR - TOP INSIDE EDGES

" " " - BLACK MARKING @ FRONT @ TOP CORNER

LEFT SINK DOOR - " " " " " " " " " " " "

" " " PAINT CHIP @ FRONT @ TOP

SINK BOX - CHIP REPAIRED @ BOTTOM - REPAIR VISIBLE
ADJUST DOOR

DONE

LAUNDRY

BUMPER RECD & CHIP @ LEFT DOOR

GABLE DAMAGED IN 2 AREAS

SCUFF ON FILLER @ FRONT OF LEFT DOOR

DONE

KITCHEN

SCUFF ON UPPER DOOR 2ND LEFT OF STOVE

SCREW COVERS RECD @ UPPER LEFT OF STOVE

UPPER STOVE GABLES - RECD TIPS

UPPER LEFT STOVE DOOR - CHIPS INSIDE

SCREW COVERS RECD @ UPPER RIGHT OF STOVE

UPPER BOX RIGHT OF STOVE - TOP INSIDE EDGES

" " " " " " " " " " " "

TOP SHELF CHIPPED

UPPER @ FRIDGE - ALL TOPS MARKED WITH 'E'

CHIP ON FAR LEFT LOWER SHELF

LOWERS ALL SCUFFS MARKED WITH TAPE

MISSING CUTLERY TRAY (SEE LAYOUT FOR SIZE)

LEFT LOWER STOVE GABLE DAMAGED (X2)

DONE

DONE