

ZANCOR Zancor Homes (Parkview) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

27May22

Closing Date:
Address:
Location:
Today's Date:
Contact(s):

Now Towns in Brooklin - Phase: 1 - Lot: Unit 83 (Block 10)
05Aug22
Mark, Anson Faria - Cell: (647) 291-7489 - (merkfaria20@gmail.com)
Carollynn, Gimeno San Jose - (carollynn.sj@gmail.com)
markfaria20@gmail.com

Email:

Zancor - Brooklin Warranty Service

Attention: Telephone:

Please Complete the following Items:

149082			149083	149084	
30-Day			зо-Дау	30-Day	
Main Bathroom- General- Item #3-	edge on left side lifting	from surface creating gap susceptible to water damages- no issue svc to re inspect	Main Bathroom- General- item #4- countertop- main bathroom countertop edge on left side lifting from surface creating gap susceptible to water damage no issue syc to re inspect	Master Ensuite- General- Item #5- trim primary bathroom	baseboard behind the bath tub curving out of the wall-syc inspect tolerance
		· ·			<u> </u>
09Aug22 /am		289	09Aug22 /am	09Aug22 /am	188
Mark 18	9AM		NEW 10		
	30-Day Main Bathroom- General- Item #3-	30-Day Main Bathroom- General- Item #3- primary bathroom laminate countertop edge on left side lifting	30-Day Main Bathroom- General- Item #3- primary bathroom laminate countertop edge on left side lifting from surface creating gap susceptible to water damages- no Issue syc to re inspect	30-Day Main Bathroom- General- Item #3- primary bathroom laminate countertop edge on left side lifting from surface creating gap susceptible to water damages-no issue svc to re inspect  30-Day Main Bathroom- Ceneral- item #4- countertop- main bathroom countertop edge on left side lifting from surface creating gap susceptible to water damage no issue svc to re inspect	Main Bathroom- General- Item #3- primary bathroom laminate countertop edge on left side lifting from surface creating gap susceptible to water damages- no issue svc to re inspect  30-Day Main Bathroom- Countertop- main bathroom countertop edge on left side lifting from surface creating gap susceptible to water damage no issue svc to re inspect  30-Day Maeter Ensuite- General- Item #5- trim primary bathroom

PBOOK -

149092	149091	149090	149089	149087	149086	149085
30-Day	30-Day	30-Day	30-Day	30-Day	30-Дау	30-Day
Other- General- item 13- kitchen window on left middle ledge	Kitchen- General- Item 12- cabinets- kitchen island toe kick gap from island side base and has slight crack- svc tp dap very small	Kitchen- General- item 11- floor between kitchen cabinets and island has a crack- Unable to find at time of inspection homeowner to send photo	Kitchen- General- Item 10- kitchen- trim- baseboard trim has large gap with flooring nd is uneven/wavy along wall kitchen window - svc inspect tolerance	Offher- General- item 8- landing- wood flooring between powder room and basement is installed and slanted- svc to measure	Other- General- item #7- wall- bedroom on right side hallway - door frame wall scratched/ peeled off when carpet was installed	Other- General- item #6- (storage) linen closet on left wall by the door frame and wall scratched, peeled off when carpet was installed
		-	_	The state of the s		
09Aug22 /am	09Aúg22 /am	09Aug22 /am	09Aug22 Jam	09Aug22 /am	09Aug22 /am	09Aug22 /am

149107	149106	149101	149100	149097	149095	
30-Day	30-Day	30-Дау	30-Day	30-Day	30-Day	
Exterior- General- item 28- balcony- 2nd floor front balcony - right	Exterior- General- item 27- balcony- floor- 2nd floor terrace wood plank decking cracked c3 bends easily when stepped on- Unable to find, svc to inspect	Garage- General-item 22- drywall- was cut and installed short in two areas of the garage then taped over the cover of the gaps first gap is to the left of the garage door. second gap is to the bottom right of the door entering the home- N/A Unfinished area	Garage - General- item 21- garage interior- concrete- two large cracks in interior garage concrete on separate sides- Conduct water test	Other- General-item 18- floor- gaps on wood flooring near 2nd floor front balcony door	Stairs- General- item 16- landing - triangle stair landing beside square landing creaking sonically and has gaps- h.o to monitor year end repair	corner has gap between window and wood frame
09Aug22 /am	09Aug22 /am	09Aug22 /am	09Aug22 /am	09Aug22 /am	09Aug22 /am	The state of the s
	ev ministra je		280	in.	280 Com 1821	

mal	Homeowner Signature:	Homeov	Date Completed: 11: 9 9/22	ted: De: P	Date Comple
	09Aug22 /am	35	Basement- General- Service to secured duct work in basement fell down	Interval	149146
	09Aug22 /am	78	Basement- General- Service to secured duct work in basement fell down	Interval	149145
	09Aug22 /am		Exterior- General- item 33- 2nd floor back terrace above exterior sliding doors caulking unfilled areas- svc touch up small area of caulking above door	30-Day	149112
	09Aug22 /am		Exterior- General- item 32- 3rd floor balcony brick/mortar filling at the comer to the right of the balcony has unfilled hole files and nor weep holes	30-Day	149111
	09Aug22 am	SE IS	Exterior- General- item 31- 3rd floor balcony siiding on left side of sliding door has a hole- svc to fill	30-Day	149110
	09Aug22 /am	***************************************	Exterior- General- item 29- caulking/sealant- 2nd floor front balcony above exterior door and side window frame caulking large unfilled areas and mulin	30-Day	149108
			crack along wood- normal not warranted		

Trade &/or Service Tech.
Signature:

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Signature:

Print Name: Four EN

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.