

Zancor Homes (Brampton) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date:
Address: 16Jun22

Location:
Today's Date:
Contact(s):
Email: Reserve Of Country Trails - Phase: 1 - Lot: 3
16Aug22

Kanwalrajjeet, S Dhillon - Cell: (647) 667-1248 - (dhillon.design@gmail.com) dhillon.design@gmail.com

Zancor - Brampton Warranty Service

Company:
Attention:
Telephone:

Please Complete the following items:

	_		
149372	149371	149369	149368
30-Day	30-Day	30-Day	30-Day
Exterior- General- The grading in the backyard is not done properly. Water stops and makes a big puddle in the backyard.	Exterior- General- The exterior sides of the garage wood are damaged. Please see image attached.	Master Ensuite- General- Free standing bathtub in master bathroom does not have a proper tile enclosure or sealant/caulking. when I bend down, I can see the wood exposed under the bathtub without any sealant or caulking.	from the main door Main Hall- General- The floor right in front of staircase on main level of the house squeaks whenever we step on it ever since we got the house keys
		The teachers	
17Aug22 /am	17Aug22 /am	17Aug22 /am	17Aug22 /am
· // //	REDIRECT TO VAL GREEN		YOUR END

Date Completed:

Homeowner Signature: 🔀

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Date Completed:

Print Name:

SOUR EN

Signature:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Outstanding Deficiencies Reserve Of Country Trails - Phase: 1 - Lot: 3

17Aug22	ading in the backyard Brampton r stops and makes a d. Warranty 1. Service 1.49372	Exterior- General- The grading in the backyard is not done properly. Water stops and makes a big puddle in the backyard.	12	30-Day	11Aug22
Add 17Aug22	terior sides of the I. Please see image Service 149371	Exterior- General- The exterior sides of the garage wood are damaged. Please see image attached.	11	30-Day	11Aug22
Add 17Aug22	Poor roofing workmanship I on the roof. All the shingles sealed. The roof also st watch the entire video suble tap to play the video on I 49370	Exterior- General- Poor roofing workmanship and cheap material on the roof. All the shingles on the roof are not sealed. The roof also appears wavy. Must watch the entire video attached. please double tap to play the video on docx	10	30-Day	11Aug22
<u>Add</u> 17Aug22	bathtub 2 per tile B end V r the	nsuite- General- bathroom does or sealant/caully or sealant/caully an see the wood without any seala	9	30-Day	11Aug22
Add 17Aug22	floor right in front of the house squeaks ver since we got the Warranty Service 149368	Main Hall- General- The floor right in front of staircase on main level of the house squeaks whenever we step on it ever since we got the house keys	00	30-Дау	11Aug22
<u>Add</u> <u>17Aug22</u>	s marks are popping Brampton main floor at the Service 149367	Main Hall- General- nails marks are popping out in the hallway on the main floor at the entrance from the main door	7	30-Day	11Aug22
Add 17Aug22	General- The basement floor has an torack on its floor- SVC TO Warranty Service 149366	Basement- General- The basement floo almost 12ft crack on its floor- SVC TO Measure	6	30-Day	11Aug22
Add 17Aug22	rcase railings have m at multiple spots. Marranty. Service 149365	Stairs- General- The staircase railings have white paint stains on them at multiple spots	S	30-Day	11Aug22
<u>Add</u> 17Aug22	upet job done very t does not have shims rg out of the carpets. properly secured properly secured 149364	Bedroom 2- General- Carpet job done very poorly in all bedrooms. It does not have shims and there are nails sticking out of the carpets. The carpet edges are not properly secured under the trims of the rooms.	4	30-Day	11Aug22
Add 17Aug22	inum Siding (Silver	Kitchen- General- Aluminum Siding (Silver trim between tile) sticking out where the kitchen tiles and hardwood joins. It is sharp and as it sticks out, it's not safe for kids in the house. It is also dirty and need touchups	ω	30-Day	11Aug22
<u>Add</u> <u>17Aug22</u>	1 step not smooth-Pitted $\frac{Bolton}{Railings}$ $\frac{Inc.}{149362}$	Stairs- General- Wooden step not smooth-Pitted areas	2	30-Day	11Aug22
Add 17Aug22	Item #1 RING~CRACK ON OTRANCED TO R-NOTED ON PDI Hardwood 149361	Living Room- General- Item #1 FOYER/HALL- FLOORING-CRACK ON 7TH BOARD FROM ENTRANCED TO LIVING FROM FOYER- NOTED ON PDI	<u>,</u>	30-Day	11Aug22
<u>Add</u> <u>17Aug22</u>	DROOM- CARPET SHIM NOT THROUGHOUT THROUGHOUT THROUGHOUT 148077	MASTER BEDROOM- FLOORING~CARPET SHIM I INSTALLED THROUGHOUT	7	PDI	<u>08Jun22</u>
1 Add 17Aug22		FOYER/HALL- FLOORING~SCRATCH ON HARDWOOD AT FIRST PLANK AT ENTRANCED TO KITCHEN FORM FOYER	ω	PDI	08Jun22
Add 15	ING~CRACK ON ITRANCED TO	FOYER/HALL- FLOORING-CRACK ON 7TH BOARD FROM ENTRANCED TO LIVING FROM FOYER	2	PDI	08Jun22
Add Appointment Trade Date	- 16	Denciency Description	Number	Туре	<u>Date</u> <u>Reported</u>

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Map / 1/2 Zancor Service Technician: Roun AEN