Enrollment:

Purchaser Name: Ryan Jin Hei Li

Phone Res:

Phone Bus: (905) 621-2828
Closing Date: August 25, 2022
Inspector: Gisella Fiore

ANCOR HOMES

Page 1 of 3

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 56 (Block 9) / 1

Plan: Address: Municiaplity:

Inspection Date: August 23, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

THERMOSTAT NOT INSTALLED AT WALL		
LIGHT FIXTURE NOT INSTALLED		
SHOWER GLASS NOT INSTALLED		
INSPECT SCRATCH AT CEILING BY SHOWER FACUET		
CHIP INSIDE LOWER LEFT CABINET AT BOTTOM GABLE		
CHIP AT TOP RIGHT CORNER OF MARBLE SURROUND AND SCRATCHES ON BOTTOM BASE		
TILE CUT INCORRECT CANNOT FIT HEAT REGISTER BEHIND TUB		
UNEVEN STIPPLE ABOVE BATHROOM DOOR AND WAVE BETWEEN WALL AND CEILING		
WIRED SHELVING NOT INSTALLED THROUGHOUT		
ATTIC HATCH UNDER SIZED		
ADJUST BALCONY DOOR		
DOWNSPOUT NOT INSTALLED AT EXTERIOR		
ADJUST GARAGE DOOR LOCK		
MOTAR REQUIRED ABOVE LENTIL AT MAIN FLOOR BALCONY		
VENT COVER DAMAGED RIGHT OF PATIO DOOR		
SIDING DENTED UPPER RIGHT CORNER EDGE ABOVE PATIO DOOR FRONT PORCH		
SCRATCHES ON FRONT PATIO CAPPING AT UPPER BALCONY ABOVE FRONT DOOR AND REAR		
BALCONY RIGHT SIDE		
CAP AT EAVESTROUGH NOT INSTALLED UPPER REAR PATIO ABOVE BALCONY DOOR		
	LIGHT FIXTURE NOT INSTALLED SHOWER GLASS NOT INSTALLED INSPECT SCRATCH AT CEILING BY SHOWER FACUET CHIP INSIDE LOWER LEFT CABINET AT BOTTOM GABLE CHIP AT TOP RIGHT CORNER OF MARBLE SURROUND AND SCRATCHES ON BOTTOM BASE TILE CUT INCORRECT CANNOT FIT HEAT REGISTER BEHIND TUB UNEVEN STIPPLE ABOVE BATHROOM DOOR AND WAVE BETWEEN WALL AND CEILING WIRED SHELVING NOT INSTALLED THROUGHOUT ATTIC HATCH UNDER SIZED ADJUST BALCONY DOOR DOWNSPOUT NOT INSTALLED AT EXTERIOR ADJUST GARAGE DOOR LOCK MOTAR REQUIRED ABOVE LENTIL AT MAIN FLOOR BALCONY VENT COVER DAMAGED RIGHT OF PATIO DOOR SIDING DENTED UPPER RIGHT CORNER EDGE ABOVE PATIO DOOR FRONT PORCH SCRATCHES ON FRONT PATIO CAPPING AT UPPER BALCONY ABOVE FRONT DOOR AND REAR BALCONY RIGHT SIDE	LIGHT FIXTURE NOT INSTALLED SHOWER GLASS NOT INSTALLED INSPECT SCRATCH AT CEILING BY SHOWER FACUET CHIP INSIDE LOWER LEFT CABINET AT BOTTOM GABLE CHIP AT TOP RIGHT CORNER OF MARBLE SURROUND AND SCRATCHES ON BOTTOM BASE TILE CUT INCORRECT CANNOT FIT HEAT REGISTER BEHIND TUB UNEVEN STIPPLE ABOVE BATHROOM DOOR AND WAVE BETWEEN WALL AND CEILING WIRED SHELVING NOT INSTALLED THROUGHOUT ATTIC HATCH UNDER SIZED ADJUST BALCONY DOOR DOWNSPOUT NOT INSTALLED AT EXTERIOR ADJUST GARAGE DOOR LOCK MOTAR REQUIRED ABOVE LENTIL AT MAIN FLOOR BALCONY VENT COVER DAMAGED RIGHT OF PATIO DOOR SIDING DENTED UPPER RIGHT CORNER EDGE ABOVE PATIO DOOR FRONT PORCH SCRATCHES ON FRONT PATIO CAPPING AT UPPER BALCONY ABOVE FRONT DOOR AND REAR BALCONY RIGHT SIDE

Enrollment:

Purchaser Name: Ryan Jin Hei Li

Phone Res: (905) 621-2828

Closing Date: August 25, 2022

Inspector: Gisella Fiore

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 56 (Block 9) / 1

Plan: Address: Municiaplity:

Page 2 of 3 Inspection Date: August 23, 2022

EXTERIOR		
PAINT	SCRATCHES / CHIPS ON DOOR TRIM RIGHT SIDE AT PATIO ABOVE FRONT DOOR	
	TOUCH UP REQUIRED AT WHITE TRIM PATIO DOOR MAIN FLOOR	
	SCRATCHES ON SLIDING BALCONY DOOR TRIM AT EXTERIOR RIGHT SIDE	
	INSPECT HOLE IN SIDING ABOVE AC	
LAUNDRY ROOM		
FLOORING	DENT ON 1ST 3RD 5TH 6TH 7TH PLANK AT ENTRANCE TO LAUNDRY	
BEDROOM #3		
NOTE:	ADJUST WINDOW HARD TO OPEN	
WALLS	CHIP IN STIPPLE RIGHT OF LIGHT FIXTURE	
MAIN BATHROOM		
COUNTERTOPS	SMALL CHIP INSIDE CABINET BELOW SINK RIGHT SIDE AT GABLE	
FOYER/HALL		
STAIRS	VARNISH REQUIRED AT TRIM BELOW RISER AT LANDING 2) SCRATCH ON 2ND AND 3RD TREAD TO 1ST LANDING - SAND AND VARNISH 3) VARNISH REQUIRED AT NEWEL POST LEFT SIDE 4) TRIM BELOW NOSING AT STAIRS TO 1ST FLOOR NOT VARNISHED	
	TRIM CUT SHORT RIGHT SIDE BY RISER AT LANDING TO 3RD FLOOR 2) REPLACE TRIM AT 6TH AT STAIRS TOO 2ND FLOOR - WATER DAMAGE	
	DENT ON 1ST TREAD AT STAIRS TO 3RD FLOOR 2) FILL STINGER AT TREAD AT 1ST LANDING TOO 3RD FLOOR 3) EXPOSED SCREWS ON OUTSIDE TREAD AT STAIRS TO 3RD FLOOR 2ND FLOOR AND MAIN FLOOR 4) WOOD CAP RAISED AT SIDE TREAD-STAIRS TOO 3RD FLOOR 5) FILL NAIL/STAPLES HOLLES IN NOSING AT PICKET AT 2ND FLOOR 6) CRACK ON NOSING AT 1ST LANDING AT STAIRS TOO 2ND FLOOR FROM MAIN FLOOR 7) CRACK ON 8TH RISER AT STAIRS FROM MAIN FLOOR TOO 2ND FLOOR BY PICKET 8) INSPECT BLACK MARKS INSIDE 9TH TREAD AT STAIRS TOO 2ND FLOOR 9) CRACK ON OUTSIDE STRINGER BY STAIRS TOO BASEMENT LEFT SIDE	
FRONT DOORS	DENT ON MAN DOOR	
BASEMENT		
NOTE:	SHUT OFF VALVE NOT INSTALLED AT HOSE TOO EXTERIOR INSPECT LEAK LEFT OF FURNACE AT WATER STACK LIGHT FIXTURE NOT INSTALLED RIGHT OF HRV	
KITCHEN		
ELECTRICAL/LIGHTING	ELECTRICAL PLUG NOT COMPLETE LEFT SIDE OF ISLAND	
CABINETS	ADJUST RIGHT GABLE AT ISLAND 2) INSPECT MARKS ON UPPER LEFT DOOR. LEFT OF HOOD FAN 3) REMOVE MARKS FROM LAST BANK OF DRAWER RIGHT OF STOVE HOOD FAN NOT INSTALLED	

Enrollment:

Purchaser Name: Ryan Jin Hei Li

Phone Res:

Phone Bus: (905) 621-2828

Closing Date: August 25, 2022
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 56 (Block 9) / 1

Plan: Address: Municiaplity:

Inspection Date: August 23, 2022

Page 3 of 3

A REFERENCE FOR FUTURE WARRA	ANTY REQUESTS.		ER TAKES POSSESSION IT WILL BE USED AS
designate to sign this form on their be	•	eir place should ensure they provide written auth	only to the vertuol/bulluer authorizing the
I have inspected my new home and I	agree that the description of the items listed of	on this form are accurate.	
	120		
Ryan Jin Hei Li	14		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
			Jan 1990
		Gisella Fiore	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2022/08/23	August 23, 2022	