

Outstanding Deficiencies

Reserve Of Country Trails - Phase: 1 - Lot: 6

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
23Jun22	PDI	9	FOYER/HALL- FRONT DOORS-RIGHT OPERATING DOOR FIXED GLASS SCRATCHED	Newmar 148353	Add	26Jul22		
23Jun22	PDI	12	FOYER/HALL- STAIRS-CHIP ON 1ST READ AT STAIRS FROM MAIN FLOOR TO FOYER	Bolton Railines Inc. 148356	Add	09Sep22		
23Jun22	PDI	17	BEDROOM #4- FLOORING-HARD FILM ON CARPET AT ENTRANCE	Zancor - Brampton Warranty Service 148361	Add	09Sep22	STAIRS THE CARPET	10 SEP 22 17 SEP 22 18 SEP 22
24Aug22	Interval	1	Bedroom 2 Ensuite- General- Bathroom doors not locking	VIA Trim and Doors Inc. 149659	Add	09Sep22		
24Aug22	Interval	3	Stairs- General- Varnish missing on 2nd step of main stairs	Princeton Painting 149661	Add	09Sep22		
24Aug22	Interval	4	Foyer- General- Service to touch up dent on wall on main floor washroom	Zancor - Brampton Warranty Service 149662	Add	09Sep22		
24Aug22	Interval	5	Foyer- General- Chip behind door	Zancor - Brampton Warranty Service 149663	Add	09Sep22		

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: 24 SEP 22
Zancor Service Technician: [Signature]