



## Service Completion Status Report

**Zancor**

Date : Oct 13, 2022

Fax :

Phone :

**ZAN08 - ZANCOR HOMES (COOKSTOWN) LTD.**

Report To: Site

Lot Number	Work Description	Status Status Date	Builder Ref #
26	MORTOR WORK AROUND FRONT WINDOWS HAS STAINED THE BLOCK WORK, EXCESS MORTOR NOT AT SEAM SHOULD BE REMOVED AND CLEANED TO ORYGINAL FINISH	Completed 10/13/2022	145991-40 S-062755
26	SPLASHED MORTAR ON BRICK ON SIDE OF HOUSES NEEDS TO BE REMOVED/ CLEANED	Completed 10/13/2022	145992-41 S-062855
27	SOME CLEANING IS REQUIRED AT THE BRICK SYSTEM, INCLUDING OUTSIDE THE FRONT AND REAR DOORS. SEALANT WORK IS REQUIRED UNDER ONE OF THE WINDOW SILLS	Completed 10/13/2022	147706 S-064771