

126

Oct 19

MSR ENSUITE

CHIPS @ BOTTOM OF RIGHT BOX

MISSING ALL BUMPERS @ LEFT BOX

AGAINST DOORS

STILL COVERED W/PLASTIC

MAIN BATH

CHIPS @ BOTTOM OF SINK BOX

RIGHT COUNTER VENEER CHIPPED

STILL COVERED W/PLASTIC

LAUNDRY

OIL

STILL COVERED W/PLASTIC

KITCHEN

FRIDGE UPPER DOORS HAVE SMALL CHIPS

AGAINST STOVE UPPER DOORS - RUB TABLES

UPPER RIGHT OF STOVE - CHIPS ON DOORS

" " " " - LAMINATE LIFTING @ UNDERSIDE

CHIP INSIDE MIDDLE P&P DRAWER

AGAINST DOORS

10-19-22

CHARLES