

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W167332 Pack Slip:194527

Service Date: Oct 21, 2022

Dui - vit	Name		Ot-tu-W	OCHEDIN E	· D		
Priority:	Normal		Status:	SCHEDULE	ט:		
BUILDER	11000500						- 44 0000
Customer:	N000508		City:	WHITBY		Received:	Sep 14, 2022
			Service Phone(s):			Time:	
Service Fax:			Site Phone:			Order:	D374361-1
Site Fax:			Lot#:	BLK 10 - 63		Phase:	PH1
_	INFORMATION			0 /	Cata	-11	
	Name: MARK ANSON FARI	A & CAROLLY			Calnu	in	
Home Phone	` '		Work Pho	ne(s):			
Cell Phone(s): 647-291-7489		Email(s):		kfaria20@gma llynn.sj@gma		
LINKED OF	DER INFORMATION (D374	1361-1)					
Customer:	N000508 ZANCOR WHITBY			Lot #:	BLK 10 - 63		
Model:	RLT-02 / MOD 2			Phase:	PH1		
SERVICE IN	ISTRUCTIONS				Cha	uplete	
BEDROOM 2 DENTED/CR LIVING ROO CHIPPED EXTERIOR- 0 THE BOTTOI	DROOM-WINDOWS-LEFT MU - GENERAL-ITEM #2- SLIDING ACKED MULLIN M- GENERAL-TEM #9- WINDO GENERAL- ITEM 26- BALCON W GENERAL- ITEM 30- 2ND FLO	G DOOR-PRIM DW FACING T Y- OTHER-2N	MARY BEDROOM S HE FRONT OF THE	ELIDING DOC E HOUSE F BALCONY- C	OR LEFT MUL FRAME/WEAT CRACKED SID	LIN REPLACI THER STRIPF DE WINDOW	ED WITH A PING INSIDE CASING AT
PARTS REC	DUIRED						
LN Item Desc		Location	Specification	Size	Options		Qty
40 BUCKIN EXTERI	IGHAM PURCH. PATIO DOOR OR JAMB REPAIR SKIN - SIDE JAMB		OTHER RPLCMN PARTS		BK 610 BUCKI	316 RIGHT INGHAM PUR DOOR	1
EXTER	IGHAM PURCH. PATIO DOOR OR JAMB REPAIR SKIN - SIDE JAMB	R MB	OTHER RPLCMN' PARTS	T 71.5 X 81.5	BUCK	316 RIGHT INGHAM PUR DOOR	1 RCH.
93 VINYL O SILL CO	CLAD SIDELITES OVER	LIV	OTHER RPLCMN' PARTS	T 24 X 97.75	BK 613	316 FJ *VSL0	26 1
Problem Desc	cription: H/b	Signod	Backer	y			
Warranty			CHARG	GEABLES			
Material \$			□ Material \$		Ĉ.		
Labour \$	-	18	Labour \$ P.O.#:)O (
Cause:							
Solution:							*

Date Completed:	Oct 21/22	Approved:		
Time:	2 hrs	Service Signature:	STEVE	





ZANCOR Zancor Homes (Parkview) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date: 27May22

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 63 (Block 10)

Today's Date:

03Aug22

Contact(s):

Mark, Anson Faria - Cell: (647) 291-7489 - (markfaria20@gmail.com)

Carollynn, Gimeno San Jose - (carollynn.sj@gmail.com)

Email:

markfaria20@gmail.com

Company: Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
147350	PDI	MASTER BEDROOM- WINDOWS~LEFT MULLIN CRACKED AT BALCONY DOOR	09Aug22 /am	
149081	30-Day	Bedroom 2- General- Item #2- sliding door- primary bedroom sliding door left mullin replaced with a dented/cracked mullin	09Aug22 /am	
149088	30-Day	Living Room- General- item #9- window facing the front of the house frame/weather stripping inside chipped	09Aug22 /am	
149104	30-Day	Exterior- General- item 25- building face- first floor window ledge /concrete molding chipped off	09Aug22 /am	not newnark
149105	30-Day	Exterior- General- item 26- balcony- other- 2nd floor front	09Aug22 /am	

		balcony- cracked side window casing at the bottom					
149109	30-Day	Exterior- General- item 30- 2nd floor sliding black exterior mullin cracked on left side where door opens		09Aug22 /am			.44
Date Completed:			Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.				
Date Completed: Oct 21/22			Trade &/or Service Tech.				

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklin - Phase: 1 - Lot: Unit 63 (Block 10)


147350 - 1 - WINDOWS~LEFT MULLIN CRACKED AT BALCONY DOOR



149105 - 1 - 1 - item 26- balcony- other- 2nd floor front balcony- cracked side window casing at the bottom



149109 - 2 - svc - item 30- 2nd floor sliding black exterior mullin cracked on left side where door opens



147350 - 2 - WINDOWS~LEFT MULLIN CRACKED AT BALCONY DOOR



149109 - 1 - 1 - item 30- 2nd floor sliding black exterior mullin cracked on left side where door opens

