Enrollment:

Purchaser Name: Jaspreet Singh

Phone Res: (905) 297-9272 Phone Bus: (647) 376-4400 Closing Date: November 17, 2022 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 92A / 1 Plan:

Address: Municiaplity:

Inspection Date: November 14, 2022

Page 1 of 3 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH			
VANITY CABINETS	HANDLES NOT INSTALLED ON CABINETS		·
	SCRATCH ON LOWER LEFT CABINET BELOW SINK 2) SCRATCH UP UPPER DRAWER		
NOTE:	UPGRADED TOLIET PAPER AND TOWEL RACKS NOT INSTALLED THROUGHOUT		
TUB	INSPECT SCRATCH ON TUB RIGHT AND LEFT SIDE		
SHARED ENSUITE			
VANITY CABINETS	ONE HANDLE NOT INSTALLED AT LOWER RIGHT CABINET		
NOTE:	ADJUST WINDOW WILL NOT CLOSE		
	SCREEN RIPPED AT OPERATING WINDOW		
	ADJUST OPERATING WINDOW IN TOLIET ROOM		
KITCHEN			
CABINETS	HANDLES NOT INSTALLED AT UPPER RIGHT CABINET RIGHT OF HOOD FAN		
	CHIP INSIDE UPPER CABINET ABOVE FRIDGE AT TOP GABLE AND BOTTOM GABLE		
	SHELF NOT INSTALLED AT LOWER RIGHT CABINET RIGHT OF FRIDGE		
	H.O REQUESTING FILL GAPS AT CROWN MOULDING RIGHT OF FRIDGE		
WINDOWS	INSPECT GLASS FOR SCRATCH ON RIGHT OPERATING SLIDING DOOR		
NOTE:	BACKSPLASH NOT INSTALLED AT KITCHEN		
MASTER BEDROOM			
NOTE:	ADJUST ATTIC HATCH	-	
LAUNDRY ROOM			
NOTE:	HARDWARE NOT INSTALLED AT CABINET THROUGHOUT		
	CHIP ON UPPER LEFT CABINET		
	FILLER GABLE RIGHT SIDE TO BE EXTENDED CUT SHORT LEAVING GAP		

Enrollment:

NOTE:

Purchaser Name: Jaspreet Singh

Phone Res: (905) 297-9272
Phone Bus: (647) 376-4400
Closing Date: November 17, 2022
Inspector: Gisella Fiore



Page 2 of 3

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 92A / 1 Plan:

Address: Municiaplity:

Inspection Date: November 14, 2022

BEDROOM #2			
WINDOWS	CRACK ON RIGHT MULLIN RIGHT FIXED WINDOW	 	
EXTERIOR			
SHINGLES	INSPECT SHINGLE RAISED ABOVE FRONT PORCH AT UPPER BEDROOM 2 WINDOW CAN SEE FROM	 	
PORCH	INSPECT CONCRETE LEFT OF PORCH SLAB BY COLUMN.	 	
BRICKS	CHECKED BRICK LEFT OF RIGHT GARAGE DOOR AT MIDDLE COLOMN AND RIGHT AND LEFT SIDE ABOVE GARAGE SEE PHOTO	 	
	CHIP ON BRICK RIGHT OF WINDOW RIGHT UP FRONT PORCH AND ABOVE DOOR LEFT WINDOW	 	
GARAGE DOORS	ADJUST WEATHERSTRIP AT RIGHT GARAGE DOOR	 	
PAINT	PAINT RIGHT GARAGE DOOR TRIM RIGHT SIDE	 	
NOTE:	FLASHING RAISED RIGHT AND LEFT SIDE ABOVE FRONT PORCH AND ADJUST TRIM RIGHT AND LEFT SIDE ABOVE FRONT PORCH AND ABOVE PEEK AT WINDOW	 	
BEDROOM #3			
FLOORING	ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW	 	
WINDOWS	CRACK ON RIGHT FIXED WINDOW MULLIN BOTTOM RIGHT CORNER	 	
BEDROOM #4			
WINDOWS	ADJUST OPERATING WINDOW BOWED	 	
BEDROOM 4 ENSUITE			
WALLS	INSPECT TILE CUT SHORT AT UPPER LEFT WALL TILE ABOVE FACUET 2) INSPECT TILE AT LEFT WALLL FOR TOLERANCE AS PER HOMEOWNER RAISED 3) AS PER HOMEWONER WALL TILE LOWER LEFT SIDE CUT SHORT	 	
VANITY CABINETS	SCRATCH INSIDE LOWER LEFT CABINET AT VANITY		
UPPER HALL			
WALLS	TOUCH UP STIPPLE AT SMOKE DETECTOR		
FOYER/HALL			
STAIRS	CHIP ON UPPER RAILING LEFT SIDE 2) H.O REQUESTING JOINT AT NEWEL AND RAILING TO BE FINISHED BETTER (ROUGH)2) FILL CORNERS OF TREAD AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR AT 1,2,3,5 TREAD STAIN VARNISH ON UPPER RAILING	 	
	PICKETS AT STAIRS TO 1ST LANDING TOO 2ND FLOOR SLANTED AT DECORATIVE SPINDLE AT AT 4TH AND 5TH TREAD TO 1ST LANDING N	 	
	CHIP ON NOSING AT STAIRS TO BASEMENT 2) CHIP ON INSIDE STRINGER BELOW NOSING AT STAIRS TO BASEMENT	 	
FRONT DOORS	INSPECT OPERATING COD OR FOR BOWED	 	
NOTE:	CHIP ON 6,7 HARDWOOD PLANK FROM RIGHT WALL	 	
	DEN - LIGHT FIXTURE NOT INSTALLED AT CEILING	 	
BASEMENT			
COLD ROOM	FLOOR DRAIN NOT INSTALLED	 	
LIVING ROOM			
FLOORING	SCRATCH 1-3 PLANK AT ENTRANCE TO LIVING FROM KITCHEN	 	
WINDOWS	LEFT FIXED WINDOW INSERT FALLING AND INSPECT RIGHT OPERATING WINDOW FOR BEING BOWED	 	
POWDER ROOM		 	

CHIP AT LOWER RIGHT CABINET BELOW SINK

Enrollment:

Purchaser Name: Jaspreet Singh

Phone Res: (905) 297-9272
Phone Bus: (647) 376-4400
Closing Date: November 17, 2022
Inspector: Gisella Fiore

ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 92A / 1

Plan: Address:

Municiaplity:

Inspection Date: November 14, 2022

ctor: Gisella Fiore Page 3 of 3

A REFERENCE FOR FUTURE WARRA	NTY REQUESTS.  designate someone to conduct the PDI in the	HOME'S CONDITION BEFORE THE PURCHASE eir place should ensure they provide written author						
I have inspected my new home and I agree that the description of the items listed on this form are accurate.								
	22182							
Jaspreet Singh								
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature					
		Gisella Fiore	Solfe					
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature					
Date (YYYY/MM/DD)	2022/11/14	November 14, 2022						