

The items listed below were released to the homeowner(s) of

Purchaser		The above items were received on this $\frac{Q^{w}}{Q^{w}}$ day of _	N/A Other	N/A Recycling and Green Bins	Homeowner Manual	House and Garage Door Keys	Lot# OK
Purchaser	1	Jaw					Site/Phase: Innisfil .
		, 2022					

## Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 37W

05Dec22	05Dec22	<u>05Dec22</u>	05Dec22	05Dec22	05Dec22	05Dec22	05Dec22	05Dec22	<u>Date</u> Reported
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	Туре
10	9	∞	9	S	4	w	2	-	Number
MASTER ENSUITE BATH- MIRROR~MIRRORS THROUGHOUT NOT INSTALLED	KITCHEN- COUNTERTOPS-BACKSPLASH NOT LINSTALLED 2) INSPECT SCUFF ABOVE DISHWASHER ON EDGE	KITCHEN- CABINETS-CHIP AT UPPER LEFT GABLE LEFT OF HOODFAN BY DRYWALL. 2) SHELF HOODFAN BY DRYWALL. 2) SHELF NOT INSTALLED AT LOWER LEFT CABINET LEFT OF HOOFAN RIGHT OF SLIDING DOOR AND AT ALL BOTTOM CABINETS 3) CHIP INSIDE UPPER LEFT CABINET BY DRYWALL INSIDE LOWER GABLE SHELF EDGE 4) CHIP AT UPPER RIGHT GABLE RIGHT OF HOODFAN CORNER 5) TOUCH UP RIGHT GABLE AT STOVE AREA SCRATCHED 6) ADJUST RIGHT LOWER CABINET RIGHT OF STOVE OCHIP AT FILLER GABLE BELOW SINK RIGHT SIDE BELOW COUNTERTOP	SHING DE	EXTERIOR- BRICKS~DRIP MARKS AND SCUFFED AREA AT UPPER RIGHT PEAK RIGHT OF WINDOW BELOW EAVESTROUGH	EXTERIOR- PAINT~DENT ON FRONT DOOR BOTTOM LEFT SIDE AND MIDDLE RIGHT	BEDROOM 2 ENSUITE- VANITY CABINETS~LARGE GAP BETWEEN GABLE AND WALL AT LOWER LEFT CABINET INSIDE AND SHELF NOT STRAIGHT	BEDROOM 3 ENSUITE- VANITY CABINETS~SMALL CHIP BELOW LEFT SINK AT GABLE	UPPER HALL- FLOORING~SQUEAK AT UPPER HALL INFRONT OF STAIRS LEFT SIDE	Deficiency Description
Central Glass 152772	AV Classic 152771	New Image Kitchens 152770	Promark Aluminum LTD. 152769	River Valley Masonry Group LTD 152768	Perfect Touch Painting 152767	New Image Kitchens 152766	New Image Kitchens 152765	Quality Rugs Canada LTD. 152764	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Add Appointment
	<							<	Item Completed
7	3<				MV				Initial

05Dec22	05Dec22	05Dec22	05Dec22	05Dec22	05Dec22
PDI	PDI	PDI	PDI	PDI	PDI
18	17	16	13	12	11
FOYER/HALL- STAIRS~NOSING RAISED AT LANDING TO MUDROOM	FOYER/HALL- STAIRS~VARNISH REQUIRED AT TRIM BELOW STRINGER AT STAIRS TO 2ND FLOOR	Foyer- General- STAIRS~EXPOSED NAILS BELOW NOSING AT RISER AT STAIRS TO 2ND FLOOR AT 2ND FLOOR AND BELOW NOSING AT 1ST LANDING TO 2ND FLOOR 2) CRACK ON OUTSIDE STRINGER BY TREAD AT LANDING AT 2ND FLOOR 3) CHIP ON STRINGER BELOW NOSING AT 1ST LANDING 2ND FLOOR	Master Ensuite- General- TUB~INSPECT SCRATCH AT EDGE OF TUB RIGHT SIDE	MASTER ENSUITE BATH- VANITY CABINETS~H.O REQUESTING SHIM BELOW SINK TO BE REPALCED	MASTER ENSUITE BATH- VANITY CABINETS-CHIP BELOW KICKPLATE BELOW SINK
Bolton Railings Inc. 152780	Perfect Touch Painting 152779	Bolton Railings Inc. 152778	Tub Net 152775	New Image Kitchens 152774	New Image Kitchens 152773
Add	Add	Add	Add	Add	Add
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.
<					
N					

Date: Zancor Service Technician:	The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.	Homeowner Signature:
----------------------------------	--	----------------------