



Zancor Homes (Parkview) Ltd.

Work Order

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Closing Date: 28Sep22

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 41 (Block 7)

Today's Date: 27Sep22

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
150440	PDI	FOYER/HALL- FRONT DOORS~ADJUST FRONT DOOR		

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

File **WO # W168830**
Pack Slip: 215754
Service Date: Dec 13, 2022

Priority:	Normal	Status:	SCHEDULED	RELEASED	
BUILDER					
Customer:	N000508	City:	WHITBY	Received:	Oct 04, 2022
Name:	ZANCOR WHITBY	Service Phone(s):		Time:	PM
Service Fax:		Site Phone:		Order:	D374339-1
Site Fax:		Lot#:	BLK 7 - 41	Phase:	PH1

RESIDENT INFORMATION

Home Owner Name:	KWADWO BOAKYE-YIADOM	Address:	N/A
Home Phone(s):		Work Phone(s):	
Cell Phone(s):		Email(s):	bqwindows@gmail.com, mameyaa2002@hotmail.com

LINKED ORDER INFORMATION (D374339-1)

Customer:	N000508 ZANCOR WHITBY	Lot #:	BLK 7 - 41
Model:	TH-1	Phase:	PH1

SERVICE INSTRUCTIONS

FOYER/HALL- FRONT DOORS-ADJUST FRONT DOOR
** TECH NOTES JAMB BETWEEN SIDELITE AND DOOR BOWED CAUSING DOOR TO RUB TALK TO STEVE FOR ANY QUESTION AS HE KNOWS HOW TO FIX I MADE THE GLASS SMALLER **

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
93	VINYL CLAD SIDELITES	ENT	GLASS ONLY - FIXED	13 X 95.375	AG14 BK/WH 4/11/4 LOWE_ARG BK	1

Problem Description:

☐ Warranty	☐ CHARGEABLES
Material \$	Material \$ <i>PIC</i>
Labour \$	Labour \$
	P.O.#:

Cause:

The door is close now, the info required to check the door against on the spring or summer if the door rubs again, required replace the side lite and find jamb between the side lites, please match appointment for spring or summer time.

Solution:

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

ALEX

As per homeowner only wants to reschedule if the continues in the spring.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7830 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G8
TEL (905) 672-1233 FAX (905) 672-1076

WO # W168830
Pack Slip: 215754
Service Date: Nov 08, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: N000508

Name: ZANCOR WHITBY

Service Fax:

Site Fax:

City: WHITBY

Service Phone(s):

Site Phone:

Lot#:

Received: Oct 04, 2022

Time: PM

Order: D374339-1

Phase: PH1

RESIDENT INFORMATION

Home Owner Name: KWADWO BOAKYE-YIADOM

Address: N/A

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

bqwindows@gmail.com,
mameyaa2002@hotmail.com

LINKED ORDER INFORMATION (D374339-1)

Customer: N000508 ZANCOR WHITBY

Lot #: BLK 7 - 41

Model: TH-1

Phase: PH1

SERVICE INSTRUCTIONS

FOYER/HALL- FRONT DOORS-ADJUST FRONT DOOR

MIR

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Take pictures

Solution:

Rebbers Jamb between side Lite & Floor Board
Causing Door to Rub

Date Completed: Nov 08/22

Approved:

Time: 1:00pm

Service Signature:

STEVE