

ZANCOR
HOMES
Zancor Homes (Parkview) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948
Work Order

Closing Date: 11Aug22

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 55 (Block 9)
Today's Date: 08Aug22
Contact(s):
Email:

Company: Newmar

Attention: Alex
Telephone: (905) 672-1233
Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
149242	PDI	MASTER BEDROOM- NOTE:~ADJUST BALCONY LOCK HARD TO OPEN AND CLOSE		
149246	PDI	DINING ROOM- NOTE:~DENT ON BALCONY DOOR ABOVE HANDLE AT MAIN FLOOR BALCONY ABOVE FRONT PORCH		

Date Completed: _____

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no
appointment time or date appear (below) on this form, it is your responsibility to arrange and
adhere to the appointment you have scheduled. Your service representative must have this form



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G8
TEL (905) 672-1233 FAX (905) 672-1076

WO # W165323
Pack Slip: 209297
Service Date: Dec 08, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000508
Name: ZANCOR WHITBY
Service Fax:
Site Fax:

City: WHITBY
Service Phone(s):
Site Phone:
Lot#: BLK 9 - 55
Received: Aug 12, 2022
Time:
Order: D374353-1
Phase: PH1

RESIDENT INFORMATION

Home Owner Name:
Home Phone(s):
Cell Phone(s):
Address:
Work Phone(s):
Email(s):

LINKED ORDER INFORMATION (D374353-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 9 - 55
Model: RLT-02 Phase: PH1

SERVICE INSTRUCTIONS

ADJUST MBED DOOR BALCONY
DINING ROOM BALCONY DOOR DENTED ABOVE HANDLE
THIS IS A 2MAN JOB
(PLEASE USE LOCK BOX - CODE 1987)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
92	2' 10" CLAD DOOR SYS 20 X 80 cut out	LIV	SLABS (ALL)	37.25 X 97.75	RIGHT STEEL 100 SERIES TYPE1 BK	1

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

Solution:

need MB patio Door Sash (see Kyle for pic)
need patio screen for kitchen patio (damaged)

Builder needs to put back cover at bottom of door.

Date Completed:


Dec 8, 2022

Approved:

Time:

Service Signature:

[Signature]
KYLE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W165323
Pack Slip:209297
Service Date: Dec 08, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000508
Name: ZANCOR WHITEBY
Service Fax: Service Phone(s):
Site Fax: Lot#: BLK 9 - 55
Received: Aug 12, 2022
Time: D374353-1
Order: PH1

RESIDENT INFORMATION

Home Owner Name:
Home Phone(s): Address:
Cell Phone(s): Work Phone(s):
Email(s):

LINKED ORDER INFORMATION (D374353-1)

Customer: N000508 ZANCOR WHITEBY Lot #: BLK 9 - 55
Model: RLT-02 Phase: PH1

SERVICE INSTRUCTIONS

ADJUST MBED DOOR BALCONY
DINING ROOM BALCONY DOOR DENTED ABOVE HANDLE
THIS IS A 2MAN JOB
(PLEASE USE LOCK BOX - CODE 1987)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
92	2' 10" CLAD DOOR SYS 20 X 80 cut out	LIV	SLABS (ALL)	37.25 X 97.75	RIGHT STEEL 100_SERIES TYPE1 BK	1

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

KYLE