## LB # 0987

## Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 79W

18Jan23	18Jan23	18Jan23	18Jan23	18Jan23	18Jan23	18Jan23	18Jan23	18Jan23	Reported
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	Туре
9	∞	7	6	V <sub>1</sub>	4	w	2	<u> </u>	Number
MASTER ENSUITE BATH- MIRROR~MIRROR THROUGHOUT NOT INSTALLED	MASTER BEDROOM- WALK IN CLOSET~STAIN AT CORNER OF CARPET IN MASTER	SHARED ENSUITE- COUNTERTOPS~CHIP AT LEFT SIDE SPLASH LEFT OF SINK	BEDROOM #4- WALLS~SEAM AT CEILING LEFT OF LIGHT FIXTURE	EXTERIOR- SHINGLES~SHINGLES AT PEAK ABOVE GARAGE LEFT SIDE DAMAGED *2	EXTERIOR- NOTE:~CAULKING AT EXTERIOR NOT COMPLETE	FOYER/HALL- STAIRS-CHIP AT 6TH TREAD FROM MAIN FLOOR TOO 1ST LANDING TO 2ND FLOOR	FOYER/HALL- STAIRS-VARNISH REQUIRED AT NEWEL POST RIGHT OF STAIR AT MAIN FLOOR 2) VARNISH REQUIRED NOSING BELOW RAILING AT STAIRS TO LANDING TO BASEMENT	KITCHEN- CABINETS~CHIP AT TOP SHELVE RIGHT OF FRIDGE ** UPPER CABINET	Deficiency Description
Metropolitan 153908 Ad	Quality Rugs Canada LTD. 153907	New Image Kitchens 153906	Foremont Drywall 153905	Trudel & Sons Roofing LTD. 153904	CJ Caulking 153903	Bolton Railings Inc. 153902	Perfect Touch Painting 153901	New Image Kitchens 153900	Trade Assigned
Add	Add	Add	Add	Add	Add	Add No	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	OS STAM NoAppoint.	NoAppoint.	NoAppoint.	Add <u>Appointment</u> [rade <u>Date</u>
	Sin Sin	3/6	<			-	M -	3/12	Item Completed
\$	8		2			2	3		Initial

STAIL FOR BOLTON REPAIR #3

Į.	ē	
illed	Hon	Hor
work	neowr	neowi
has	Ē	er
been	ackno	Homeowner Signature:
tialled work has been completed in a workman like	le Homeowner acknowledges and accepts that al	ıre:
ed in	and	
a work	accepts	
ทยท	that	
11/2	al	7.

The Homeowner acknowled initialled work has been commanner to their satisfaction. Date: Zancor Service Technician: