

BRAH

8AM - Monday

Outstanding Deficiencies
Caledon Club - Phase: 1 - Lot: 105A - Model: Greystone (30-03) Elev B 3 Bedroom

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date
09Dec22	PDI	1	KITCHEN- COUNTERTOPS-REMOVE PENCIL MARKS FROM EDGE INFRONT OF SINK	Assign	Brian	March 6 / 23
09Dec22	PDI	6	UPPER HALL- FLOORING-LARGE HUMPS IN FLOOR AT ENTRANCE TO BEDROOM 2	First Canadian Hardwood 152921	Add	NoAppoint.
09Dec22	PDI Seasonal	8	Exterior- General- PAINT-EXTERIOR PAINT NOT COMPLETE	Perfect Touch Painting 152923	Add	03Mar23
09Dec22	PDI	9	Garage- General- NOTE:-GARAGE INSIDE NOT PAINTED	Perfect Touch Painting 152924	Add	03Mar23
09Dec22	Interval	1	Throughout- General- green tape throughout	Perfect Touch Painting 152932	Add	03Mar23
20Dec22	Interval	2	Stairs- General- varnish required due to Bolton repair	Perfect Touch Painting 153446	Add	03Mar23
06Jan23	Interval	3	Garage- General- temp garage doors installed	Abbey Overhead Doors Inc. 153605	Add	NoAppoint.
09Feb23	Interval	4	Bedroom 2 Ensuite- General- shower rod missing	Icon Plumbing & Heating 154506	Add	NoAppoint.