

#### NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

WO # W179046 Pack Slip:214091

Service Date: Mar 17, 2023

Priority: Normal Status: **SCHEDULED** RELEASED **BUILDER** Customer: N000531 City: **CALEDON** Received: Feb 22, 2023 Name: ZANCOR CALEDON CLUB Time: Service Phone(s): Service Fax: Site Phone: Order: D383569-1 Site Fax: Lot#: 147A Phase:

RESIDENT INFORMATION

Home Owner Name:

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

uppalapati010@gmail.com,

fangyman123@gmail.com

LINKED ORDER INFORMATION (D383569-1)

Customer:

N000531 ZANCOR CALEDON CLUB

Lot #:

147A

Model:

38-04 GRANVIEW (RR UPG)/LOT 147A (CB)

Phase:

**SERVICE INSTRUCTIONS** 

FOYER/HALL FRONT DOORS-CHIPS ON ASTRICAL AT FRONT DOOR \*\*PLEASE GET ALL PAPERWORK SIGNED THANK YOU \*\*

ADD:

FOYER/HALL- FRONT DOORS-REPLACED WEATHER STRIP AT FRONT DOOR TORN 2) OPERATING FRONT DOOR

WEATHERSTRIP TOBE REPLACED AT BASE PEELING

LIVING ROOM- WINDOWS-SCREEN NOT INSTALLED AT WINDOW

LAUNDRY ROOM- WINDOWS-SCREEN NOT INSTALLED AT WINDOW

BEDROOM #4- WINDOWS-H.O REQUESTING TO CHANGE SCREEN BOWED

BEDROOM #3- WINDOWS-RIPPED SCREEN AT OPERATING WINDOW

BEDROOM #2- WINDOWS-ADJUST OPERATING WINDOW- MAKING NOISE

FOYER- GENERAL- FRONT DOOR GLASS - STRESS CRACK

DARTS BEALURED

PARTS REQUIRED					
LN Item Description	Location	Specification	Size	Options	Qty
11 NEWMAR VINYL CASEMENT	RGT/ LIV/DIN	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 55.125		1
40 NEWMAR VINYL CASEMENT ASTRAGAL & WEATHERSTRIP	ENS.2/LND	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 43.125	~	1
110 NEWMAR VINYL CASEMENT	LFT/ B4	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 43.125		1
141 5' 8" CLAD DOOR SYS	ENT	OTHER RPLCMNT PARTS	72 X 97.75	CB 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
142 E130_STYLE DOORLITE	ENT	DOORLITES	20 X 80	E130_STYLE DOORLITE CLR CLR LOWE_ARG 3T/19/3T	2
151 NEWMAR VINYL CASEMENT	В3	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 63.125		1

Problem Description:

Warranty Material \$ Labour \$	CHARGEABLES  Material \$ Labour \$ P.O.#:
Cause:	
Solution:	
Date Completed: MACM 17, 2023	Approved:
Time:	Service Signature:RAY





ZANCOR Zancor Homes (Caledon) Ltd. Warranty Services Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date: 23Feb23

Address:

Location:

Caledon Club - Phase: 1 - Lot: 147A

Today's Date:

01Feb23

Contact(s):

Emall:

Company:

Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

DAI	Туре	Issue	Appt. Date/Time	Notes
154265	PDI	LIVING ROOM- WINDOWS~SCREEN NOT INSTALLED AT WINDOW		V
154271	PDI	FOYER/HALL- FRONT DOORS~CHIPS ON ASTRICAL AT FRONT DOOR	/	Daye.
154272	PDI	FOYER/HALL- FRONT DOORS~REPLACED WEATHER STRIP AT FRONT DOOR TORN 2) OPERATING FRONT DOOR WEATHERSTRIP TO BE REPLACED AT BASE PEELING	H <sub>3</sub>	2/
154277	PDI	LAUNDRY ROOM- WINDOWS~SCREEN NOT INSTALLED AT WINDOW		4
154281	PDI	BEDROOM #4-		1/

		WINDOWS~H.O REQUESTING TO CHANGE SCREEN BOWED	9
154283	PDI	BEDROOM #3- WINDOWS~RIPPED SCREEN AT OPERATING WINDOW	9/
154290	PDI	BEDROOM #2- WINDOWS~ADJUST OPERATING WINDOW- MAKING NOISE	

Date Completed:	Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.
Date Completed;	Trade &/or Service Tech.
	Signature:
	Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.


Newmar / Casa Bella Mail - FW: Caledon Club lot 147A - PDI Appointment https://mail.google.com/mail/u/0/?ik=8672e0885e&view=pt&search=a...





Solvenia State Control of the		
Trans		
Wald.		
See Annie See An		
NAME OF SOME SOME STATE OF THE PARTY OF THE		
n-e		
Little of the state of the stat		
**************************************		
Activities records (Activities activities)		
Terini		
(9)		
Men the some wide parts on application of applications of the sound of		
Nubfer .		
material and the second		
I will make particular		
1-00-100 to 10-10-10-10-10-10-10-10-10-10-10-10-10-1		
For an information of the second of the seco		
wiene,		
President de la companya de la compa		
Process and the state of the st		
Silver p. Miles a silver beautiful in the silver beaut		
We complied a connection first between the beament steering plan regions and the plan is to propose and the steering the steering steering and the steering	specific sets from the direct g	

Newmar / Casa Bella Mail - FW: Caledon Club lot 147A - PDI Appointment https://mail.google.com/mail/u/0/?ik=8672e0885e&view=pt&search=a...



154265 - 1 - WINDOWS~SCREEN NOT INSTALLED AT WINDOW



154272 - 1 - FRONT DOORS~REPLACED
WEATHER STRIP AT FRONT DOOR TORN 2)
OPERATING FRONT DOOR WEATHERSTRIP TO
BE REPLACED AT BASE PEELING




154277 - 1 - WINDOWS~SCREEN NOT INSTALLED AT WINDOW



154271 - 1 - FRONT DOORS~CHIPS ON ASTRICAL AT FRONT DOOR



154272 - 2 - FRONT DOORS~REPLACED WEATHER STRIP AT FRONT DOOR TORN 2) OPERATING FRONT DOOR WEATHERSTRIP TO BE REPLACED AT BASE PEELING



154283 - 1 - WINDOWS~RIPPED SCREEN AT OPERATING WINDOW



154290 - 1 - WINDOWS-ADJUST OPERATING WINDOW- MAKING NOISE




154290 - 1 - WINDOWS~ADJUST OPERATING WINDOW- MAKING NOISE



154908 - 1 - 1 - front door glass - stress crack

154908 - 2 - 2 - front door glass - stress crack



154265 - 1 - WINDOWS~SCREEN NOT INSTALLED AT WINDOW



154272 - 1 - FRONT DOORS~REPLACED WEATHER STRIP AT FRONT DOOR TORN 2) OPERATING FRONT DOOR WEATHERSTRIP TO BE REPLACED AT BASE PEELING



154277 - 1 - WINDOWS~SCREEN NOT INSTALLED AT WINDOW



154271 - 1 - FRONT DOORS~CHIPS ON ASTRICAL AT FRONT DOOR



154272 - 2 - FRONT DOORS~REPLACED WEATHER STRIP AT FRONT DOOR TORN 2) OPERATING FRONT DOOR WEATHERSTRIP TO BE REPLACED AT BASE PEELING



154283 - 1 - WINDOWS~RIPPED SCREEN AT OPERATING WINDOW

