



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 26Jan23

Address:

Location:

Today's Date:

Contact(s):

Email:

Caledon Club - Phase: 1 - Lot: 142A
08Mar23

Pardeep Goel - Work: (647) 786-5394 - (goel.pardeep@gmail.com)
Gupta Sakshi - Work: (647) 786-9728 - (guptasakshi@gmail.com)
goel.pardeep@gmail.com

Company:

Attention:

Telephone:

Fax:

First Canadian Hardwood
Nicholas

(905) 850-7220

(905) 850-2641

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
153629	PDI	UPPER HALL- FLOORING-CHIP ON 10TH HARDWOOD PLANK LEFT OF HEAT REGISTER INFRONT OF TRIM TO SLIDING DOOR		
153640	PDI	KITCHEN- FLOORING-CHIP ON 10TH HARDWOOD PLANK LEFT OF HEAT REGISTER INFRONT OF TRIM TO SLIDING DOOR		
153644	PDI	FOYER/HALL- FLOORING-CHIP AT 1ST HARDWOOD PLANK INFRONT OF STAIRS TO 2ND FLOOR LEFT SIDE 2) WRONG COLOUR PUTTY USED TO		

FILL HOLES BELOW
RISER AT STAIRS TO
2ND FLOOR

Date Completed: Mo 2/1/23

Homeowner Signature:
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.


153629 - 1 - FLOORING~SCRATCH AT 2ND PLANK
RIGHT SIDE INSIDE LINEN CLOSET 2) SMALL
CHIP AT FIRST HARDWOOD PLANK BY NOSING
AT STAIRS TO MAIN FLOOR LEFT SIDE




153629 - 2 - FLOORING~SCRATCH AT 2ND PLANK
RIGHT SIDE INSIDE LINEN CLOSET 2) SMALL
CHIP AT FIRST HARDWOOD PLANK BY NOSING
AT STAIRS TO MAIN FLOOR LEFT SIDE



153629 - 3 - FLOORING~SCRATCH AT 2ND PLANK
RIGHT SIDE INSIDE LINEN CLOSET 2) SMALL
CHIP AT FIRST HARDWOOD PLANK BY NOSING
AT STAIRS TO MAIN FLOOR LEFT SIDE



153629 - 4 - FLOORING~SCRATCH AT 2ND PLANK
RIGHT SIDE INSIDE LINEN CLOSET 2) SMALL
CHIP AT FIRST HARDWOOD PLANK BY NOSING
AT STAIRS TO MAIN FLOOR LEFT SIDE




153640 - 1 - FLOORING~CHIP ON 10TH
HARDWOOD PLANK LEFT OF HEAT REGISTER
INFRONT OF TRIM TO SLIDING DOOR

153640 - 2 - FLOORING~CHIP ON 10TH
HARDWOOD PLANK LEFT OF HEAT REGISTER
INFRONT OF TRIM TO SLIDING DOOR



153644 - 1 - FLOORING~CHIP AT 1ST HARDWOOD PLANK INFRONT OF STAIRS TO 2ND FLOOR LEFT SIDE 2) WRONG COLOUR PUTTY USED TO FILL HOLES BELOW RISER AT STAIRS TO 2ND FLOOR



153644 - 2 - FLOORING~CHIP AT 1ST HARDWOOD PLANK INFRONT OF STAIRS TO 2ND FLOOR LEFT SIDE 2) WRONG COLOUR PUTTY USED TO FILL HOLES BELOW RISER AT STAIRS TO 2ND FLOOR



153644 - 3 - FLOORING~CHIP AT 1ST HARDWOOD PLANK INFRONT OF STAIRS TO 2ND FLOOR LEFT SIDE 2) WRONG COLOUR PUTTY USED TO FILL HOLES BELOW RISER AT STAIRS TO 2ND FLOOR

