## Shoreline Point - Phase: 1 - Lot: 109 - Model: The Coral (60-04) Elev C **Completed Deficiencies**

	0.0					
05Apr23	05Apr23	05Apr23	05Apr23	05Apr23	05Apr23	Date Reported
PDI	PDI	PDI	PDI	PDI	PDI	Type
9	00	6	S	4	2	Number
NCE LIGHTS NOT	KITCHEN- CABINETS-SCREW THROUGH KICKPLATE RIGHT OF FRIDGE 2) CHIP AT VALANCE RIGHT OF STOVE BELOW GLASS 3) ADJUST ISLAND SLANTED 4) SMALL CHIP AT ISLANDING FACING LIVING 5) SCRATCH AT LOWER LEFT HANDLE RIGHT OF STOVE 6) SCRATCH ON LOWER RIGHT CABINET HANDLE RIGHT OF BANK OF DRAWERS  Complete - As per Trade - ad - Group Close	MASTER ENSUITE BATH- VANITY CABINETS-CHIP AT BOTTOM GABLE BELOW LEFT SINK 2) SCREW HOLES AT 3RIN BANK OF DRAWERS 1) CHIP AT BOTTOM BANK OF DRAWERS 4) SCRATCH ON LOWER LEFT HANDLE BELOW RIGHT SINK Complete - As per Trade - mi - Group Close	CARPET SHIM AT ER REQUESTING ITING LOW	MAIN BATHROOM- VANITY CABINETS~DAMAGE ON THE INSIDE LOWER LEFT CABINET AT SCREW HOLE FOR HANDLE  **Complete - As per Trade - ad - Group Close**	FOYER/HALL- STAIRS~SCRATCH ON NEWEL AT FIRST FLOOR TO 2ND FLOOR FROM FRONT DOOR  Complete - As per Trade - ad - Group Close	Number Deficiency Description
(Mykon Electric North Ltd) 155905	(New Image Kitchens)	Image Kitchens 155902	(Quality Rugs Canada LTD.)	(New Image Kitchens) 155900	(VIP Railings Inc.) 155899	Trade Assigned
Add	Add	新	Add	Add	Add	Add Trade
No Appoint.	NoAppoint.	X	NoAppoint.	No Appoint.	NoAppoint.	Appointment Date

momeowner Signature:

The Homeowner acknowledges and accepts that all initialed work has been completed in a workman like manner to their satisfaction.

ADD
ADDUST DEERS (P MSTR CLOSET, BORMS, CORET, MAIN HALL
REPLACE SCREENS (P MSTR & FAMILY)
CLOSET DOOR DOOR HANDLES MISS ALIGNED WIRED

## Shoreline Point - Phase: 1 - Lot: 109 - Model: The Coral (60-04) Elev C **Outstanding Deficiencies**

03May23 Interval	05Apr23 P	05Apr23 P	05Apr23 P	Date Reported T	
erval	PDI	PDI	PDI	Туре	
-	7	ω	H	Number	
Kitchen- General- REPLACE FRIDGE ATER LINE (HAS KINKS/BENT)	LIVING ROOM- FLOORING~RAISED HARDWOOD PLANK INFRONT OF LINEN CLOSET AT HALLWAY.	Foyer- General- STAIRS~RISER BELOW NOSING AT STAIRS TO BASEMENT SCREW HOLES VERY VISIBLE.	EXTERIOR- PAINT~NOT COMPLETE	Number Deficiency Description	
Nota Plumbing & Heating Inc. 156762	First Canadian Hardwood 155903	Perfect Touch Painting 155906	Perfect Touch Painting 155898	Trade Assigned	
Add	Add	Add	Add	Add Trade	
Add NoAppoint.	Add NoAppoint.	Add NoAppoint	Add NoAppoint.	Add Appointment Trade Date	

Homeowner Signature: \_

The Homeowner acknowledges and accepts that all initialed work has been completed in workman like manner to their satisfaction.