

✕ RE: Lot 143 Shoreline- Pending Conce...

Deficiencies on Shoreline Point - 1 - 143

For Kingsview Carpentry

FRAMER:
DAN B.M.
May 31, 2023

DAI	Type	Issue	Appt. Date / Time	Notes
156266	Interval	Basement- General- Pack and add 2 X 6 infront of existing of 2 x 6 right and left side below steel beam - SEE PHOTO	DK	
				Homeowner Signature: The Homeowner acknowledges and accepts that all Initialed work has been completed in a workman like manner to their satisfaction.
156268	Interval	Basement- General- Pack over top cracked bottom play 2 by 4 below stairs see photo #3	DK	
156269	Interval	Basement- General- Replace 2 by 6 support at landing due to crack 2 by 6	DK	