Enrollment:

Purchaser Name: Tianxu Liu

Hui Wang

Phone Res:

Phone Bus: (647) 390-4553

Closing Date: July 13, 2023



Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 54W / 3

Plan: Address: Municiaplity:

Inspection Date: July 11, 2023

Inspector: Gisella Fiore Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

RAILING MISSING SCREW PLUGS AT JULIET BALCONY AT SECOND FLOOR CHIP AT LEFT NEWEL POST AT UPPER HALL TOP CAP SHARED ENSUITE VANITY CABINETS CHIP INSIDE BOTTOM LEFT CABINET BELOW LEFT SINK. CHIPPED AT RIGHT SIDE, SPLASH, RIGHT OF SINK BEDROOM 4 ENSUITE VANITY CABINETS SMALL CHIP AT BOTTOM GABLE BELOW SINK. FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING. RIGHT AND LEFT SIDE AT ISLAND GABLE PEELING AT FLOOR LINE.	
SHARED ENSUITE VANITY CABINETS CHIP INSIDE BOTTOM LEFT CABINET BELOW LEFT SINK. CHIPPED AT RIGHT SIDE, SPLASH, RIGHT OF SINK BEDROOM 4 ENSUITE VANITY CABINETS SMALL CHIP AT BOTTOM GABLE BELOW SINK. FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
VANITY CABINETS CHIP INSIDE BOTTOM LEFT CABINET BELOW LEFT SINK. CHIPPED AT RIGHT SIDE, SPLASH, RIGHT OF SINK BEDROOM 4 ENSUITE VANITY CABINETS SMALL CHIP AT BOTTOM GABLE BELOW SINK. FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
CHIPPED AT RIGHT SIDE, SPLASH, RIGHT OF SINK BEDROOM 4 ENSUITE VANITY CABINETS SMALL CHIP AT BOTTOM GABLE BELOW SINK. FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
BEDROOM 4 ENSUITE VANITY CABINETS SMALL CHIP AT BOTTOM GABLE BELOW SINK. FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
VANITY CABINETS SMALL CHIP AT BOTTOM GABLE BELOW SINK. FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
FOYER/HALL STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
STAIRS CRACK ON OUTSIDE TRIM AT STRINGER AT STAIRS LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
LIBRARY/DEN WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
WALLS OVERCUT AT LIGHT FIXTURE POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
POWDER ROOM SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
SINK/FAUCET/PLUMBING FACUET SPRAYING WATER. KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
KITCHEN FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
FLOORING TILE RIGHT AND LEFT OF SLIDING DOOR LARGE GAP - TILE CUT SHORT. CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
CABINETS UPPER RIGHT CABINET RIGHT OF HOODFAN NOT INSTALLED AND DAMAGED. CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
CHIP INSIDE 3RD BANK OF DRAWER LEFT OF STOVE. ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
ADJUST UPPER RIGHT CABINET RIGHT OF ENTRANCE TO DINING.	
RIGHT AND LEFT SIDE AT ISLAND GABLE PEELING AT FLOOR LINE.	
DINING ROOM	
WALLS WALL BOWED LEFT OF JULIET CAN SEE FROM BELOW	

Enrollment:

Purchaser Name: Tianxu Liu

Hui Wang

Phone Res:

Phone Bus: (647) 390-4553
Closing Date: July 13, 2023
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 54W / 3 Plan:

Address: Municiaplity:

Inspection Date: July 11, 2023

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. o designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASI neir place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
Tianxu Liu	Wanter	Hui Wang	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	YL.
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Data (VVVV/MM/DD)	2022/07/11	luly 11 2022	