Enrollment:

Purchaser Name: Tajinder Singh Saini

Kiranjot Kaur

Phone Res:

Phone Bus: (647) 300-5449 **Closing Date:** July 24, 2023

ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 5B / 1B Plan:

Address: Municiaplity:

Inspection Date: July 18, 2023

Inspector: Gisella Fiore Page 1 of 3

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
VANITY CABINETS	CHIP AT BOTTOM LEFT GABLE BELOW LEFT SINK.	
FAUCETS/PLUMBING	UPGRADED TOLIET PAPER HOLDERS NOT INSTALLED THROUGHOUT.	
	ADJUST DOOR TO TOLIET.	
COUNTERTOPS	SCRATCHES ON COUNTERTOP IN BETWEEN SINK.	
FLOORING	REMOVE STAINS ON GROUT INFRONT OF RIGHT SINK.	
MASTER BEDROOM		
FLOORING	REMOVE STAINS OFF CARPET BELOW WINDOW.	
SHARED ENSUITE		
VANITY CABINETS	CHIP AT COUNTERTOP LEFT OF SINK AT LIP.	
WALLS	2ND COAT OF PAINT REQUIRED IN TOLIET ROOM.	
FLOORING	REMOVE STAINS OFF GROUT ON FLOOR TILE	
TRIM	ADJUST DOOR TO SHARED BATH CANNOT CLOSE.	
ELECTRICAL/LIGHTING	CRACKED RIGHT LIGHT FIXTURE	
BEDROOM #3		
FLOORING	REMOVE DEBRIS FROM CARPET BELOW AT ENTRANCE TO SHARED.	
	CARPET AT ENTRANCE TO CLOSET LEFT SIDE LIFTING.	
NOTE:	ADJUST TOLIET NOT STRAIGHT.	
	ADJUST TUB KICK NOT STRAIGHT.	
LAUNDRY ROOM		
SINK/FAUCET/PLUMBING	FACUET MAKING NOISE WHEN TURNED OFF. AND LEAKING BELOW.	
WINDOWS	CRACK ON OPERATING WINDOW.	
FLOORING	CHIP AT TILE LEFT HEAT REGISTER.	

Enrollment:

Purchaser Name: Tajinder Singh Saini

Kiranjot Kaur

Phone Res:

Phone Bus: (647) 300-5449
Closing Date: July 24, 2023
Inspector: Gisella Fiore



Page 2 of 3

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 5B / 1B

Plan: Address:

Municiaplity: Inspection Date: July 18, 2023

BEDROOM 3 ENSUITE		
VANITY CABINETS	CHIP ON LEFT SIDE SPLASH. LEFT FOR A SINK.	
	SMALL CHIP AT GABLE BELOW SINK.	
UPPER HALL		
FLOORING	CHIP AT HARDWOOD AT ENTRANCE TO BEDROOM 4.	
	CHIP ON HARDWOOD PLANK AT ENTRANCED TO BEDROOM 2.	
FOYER/HALL		
STAIRS	SCRATCH ON RAILING AT SECOND FLOOR	
	SHIP RAILING BY NEWELL POST AT MAIN FLOOR RIGHT SIDE	
	CHIP ON OUTSIDE STRINGER BELOW FOURTH AND FIFTH TRIED UPSTAIRS TO SECOND FLOOR	
	CHIP ON NEWEL POST RIGHT SIDE BY TREAD AT MAIN FLOOR	
	CRACK ON NOSING AT FRONT ENTRANCE.	
FRONT DOORS	DENT ON FRONT DOOR TRIM AT LEFT OPERATING DOOR.	
NOTE:	DENTS ON MAN DOOR.	
	STAINS ON GROUT AT MUD ROOM	
TRIM	H.O REQUESTING TO ADJUST DOORS THROUGHOUT. HINGES NOT FLUSH DOORS DO NOT	
	CLOSE.	
	DOOR TO MUD ROOM CLOSET CANNOT CLOSE AND CUT AT BOTTOM	
	H.O NOT ACCEPTING DRYWALL FINISH IN MUDROOM AND CLOSET. SEAMS VISIBLE.	
EXTERIOR		
NOTE:	FILL GAPS ABOVE FRONT DOOR AT EXTERIOR BETWEEN SLIDING AND BRICK.	
	CHIP AT 1ST TREAD AND HOLE IN SLAB AT FRONT PORCH.	
	CRACKED STONE LEFT OF STAIRS	
	DENT ON RIGHT SIDE OF COPING ABOVE FRONT PORCH	
	CAULKING REQUIRED A COLD ROOM VENTS.	
BASEMENT		
NOTE:	FURNACE TURNED OFF DUE FREEZING H.O REQUESTING TO HAVE REPORTED.	
POWDER ROOM		
NOTE:	SECURE BOTTOM GABLE TO BACK PANEL.	
	INSPECT BOTTOM LEFT CABINET SCRATCHED	
	COUNTERTOP SCRATCHED LEFT OF SINK.	
WINDOWS	ADJUST WEATHER STRIP AT WINDOW.	
DINING ROOM		
FLOORING	OVER CUT AT HRV	
	CHIP ON 2 MOLD AT ENTRANCE FROM KITCHEN TO DINNING.	
	CHIP ON 1ST HARDWOOD BELOW WINDOW AT HEAT REGISTER.	

Enrollment:

Purchaser Name: Tajinder Singh Saini

Kiranjot Kaur

Phone Res:

Phone Bus: (647) 300-5449
Closing Date: July 24, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 5B / 1B

Plan:

Address: Municiaplity:

Page 3 of 3 Inspection Date: July 18, 2023

KITCHEN			
CABINETS	UPPER CABINET ABOVE FRIDGE NOT INSTALLED.		
	CHIP ON UPPER RIGHT AND LEFT GABLE AT FRIDGE.		
	CHIP AT BOTTOM GABLE LEFT OF FRIDGE.		
	CRACK AT FILLER GABLE RIGHT SIDE AT DW		
	SECURE STRIP EDGE AT ISLAND LEFT SIDE.		
	EXPOSED SCREW AT ISLAND GABLE RIGHT SIDE AT FLOOR LINE.		
WALLS	GROUT REQUIRED AT BACKSPLASH TILE RIGHT OF FRIDGE.		
	H.O REQUESTING BACK SPLASH TILE TO BE USED BEHIND STOVE INSTEAD OF GROUT FILLED.		
	LEFT SIDE.		
SINK/FAUCET/PLUMBING	SINK LEAKING TO BELOW AT ISLAND		
LIVING ROOM			
FLOORING	CHIP ON 19, 23, 25 PLANK AT ENTRANCE FROM KITCHEN AND 4,12 PLANK FROM FIREPLACE.		
LIBRARY/DEN			
FLOORING	CHIP ON, 7TH PLANK AT ENTRANCED TO DENT RIGHT SIDE.		

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Tajada Sl Tajinder Singh Saini Kiranjot Kaur Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature July 18, 2023 Date (YYYY/MM/DD) 2023/07/18