Robert Cioffi

ANCOR INNISAL

360 W Call Nathan it issue LOCK Box code 1290

By trailer handle

From:

Nathan Simas <nathan@zancorhomes.com>

Sent:

Monday, July 17, 2023 2:13 PM

To:

Sandy Costa; Nicholas P D.A.R.T Electric Ltd.; Daniela Ascenzo;

cjcompanyltd@rogers.com; mbrass.rivervalley@hotmail.com; carlos@boltonrailing.com; John DiFabio; Frank Falusi; Joseph Ferrari; mikel@iconplumbingandheating.com; Robyn Holmes; Tania Montagner; Amy Palombo; papageo32@gmail.com; Melissa Green; Shonnessa Facey; carmine@fchardwood.com; rob@smart-tech.ca; Robert Cioffi; Andrew

Spanjevic; Matt Storring

Cc:

Carmelo; Chris DiGenova

Subject:

FW: LOT 360W QC

Good Afternoon

Please have the following completed, by the next of this week.

Thank you,

Nathan Simas **Finishing Supervisor** Belle Aire Shores Cell # 416-791-9862 nathan@zancorhomes.com



From: Chris DiGenova <chris@zancorhomes.com>

Sent: Monday, July 17, 2023 10:52 AM

To: Domenic DiGenova < domenic@zancorhomes.com >; Anthony Riccardi < anthony@zancorhomes.com >

Subject: LOT 360W QC

360W QC BELLE AIRE SHORES

EXTERIOR:

INSTALL GARAGE DOORS – ABBEY OUTLET IN GARAGE NOT IN WALL - DART CONNECT GAS LINE TO METER - TRIFLAME HEAT FINISH — NATIONAL (JULY 25TH)

DAP BAY WINDOW — WYECROFT

NAIL IN WALL LEFT OF BAY WINDOW — ZANCOR

SCREW AND NAIL HOLES IN WINDOW TRIM RIGHT OF

FIRE PLACE — ZANCOR

WINDOW LEFT OF FIRE PLACE DOESN'T CLOSE FULLY —

NEWMAR

BROKEN BAY WINDOW SECOND FROM RIGHT —

NEWMAR

KITCHEN:

THE WALL STREET

SLIDING DOOR FRAME BROKEN – NEWMAR
COUNTER TOPS NEEDED – REDSTONE
REMOVE PENCIL + GLUE MARK UPPER CABINET LEFT
OF COOK TOP - NIK
CHIP IN UPPER HABLE BELOW COOK TOP – NIK
ALIGN ALL CABINETS – NIK
CHIP @ FRIDGE ENCLOSURE TOP RIGHT – NIK
FAUCET NEEDED – ICON
HANDLE + SHELVES @ PANTRY NOT COMPLETE –
WYECROFT
PAINT MUDROOM/KITCHEN DOOR – PERFECT TOUCH
NAIL ABOVE OUTLET @ MUDROOM DOOR – ZANCOR
DAP MUDROOM DOOR TO WALL – ZANCOR

CHIP @ DRAWER RIGHT OF FRIDGE ENCLOSURE – NIK

CABINET ABOVE WALL OVEN MISSING TOP STOPPER –

NIK

TOP STOPPER LIGHT OF PIE CABINET DOESN'T WORK –

NIK

NATHANS NOTES:

BACK TRIM HARDWARE NOT INSTALLED - WYECROFT SHOWER MISSING HARDWARE + LAUNDRY FAUCET - ICON

TUBS/SHOWERS NOT CAULKED – A/V
DOOR WAY HEADERS SHORT 9 DOORS ON 2ND FLOOR ZANCOR

EXTEND DRYER VENT – NATIONAL LAUNDRY TILE BASEBOARDS – A/V HVAC FINISH JULY 25 DATA FINISH – SMART TECH

PICKET MISSED ON LANDING - BOLTON

KITCHEN TILE REPAIR - A/V

KITCHEN BULK HEAD NO PROPER (NEEDS TO BE

REBUILT) - KINGSVIEW

H/W OVERCUT @ ARCHWAY FROM FOYER TO DINING ROOM – FCH