

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W19762 Pack Slip:5919

Service Date: Oct 12, 2023

Priority:	Normal	Status:	SCHEDULED			
BUILDER						
Customer:	8030030	City:	OAKVILLE	Received:	Oct 10, 2023	
Name:	ZANCOR THE BRANCH COND	OS Service Pho	ne(s):	Time:		
Service Fax:		Site Phone:	(416) 566-2066	Order:	H801166-1	
Site Fax:		Lot#:	5TH FLOOR	Phase:	511	
RESIDENT	INFORMATION					
Home Owne	r Name:	Ad	dress:			
Home Phone(s):		Wo	Work Phone(s):			
Cell Phone(s):		Em	Email(s):			
LINKED OF	RDER INFORMATION (H80116	56-1)		***************************************		
Customer:	8030030 ZANCOR THE BRANCH	House Model: 5T	House Model: 5TH FLOOR			
_ot #:	5TH FLOOR Phase:		Elevation:	Elevation:		
SERVICE II	NSTRUCTIONS	e Server (1994) (1994) (1994) (1994) (1994) (1994) (1994) (1994) (1994) (1994) (1994) (1994) (1994)				
**CLOSING	ON NOVEMBER 1ST 2023***					
NVESTIGAT	E AND CORRECT					
DAI #163846 - PDI - MASTER BEDROOM - WINDOWS - MULIN TRIM SHORT UPPER RIGHT CORNER - Not Newmar Issue. (See pic)						
				15500	(See pic)	
DAI #163849	- PDI - BEDROOM 2 - WINDOWS	S - DAMAGED MULLIN I	EFT OF WINDOW— CO	mpleted.		
<b>1ΔΙ #16385</b> Ω	- PDI - BEDROOM 2 - WINDOWS	S - SCREEN AND CRAN	IKS NOT INSTALLED THE	OUCHOUT BOTH	REDROOM	
VINĎOWS ~	-Completed	- SORLLIN AND CRAIN	ING NOT INSTALLED THE	COOGHOOT BOTH	BEDROOM	
	Jimperen			A	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	
Problem Des	cription:					
Warranty	CH		CHARGEABLES	ARGEABLES		
Material \$		Ma	terial \$			
.abour \$		Lab	our \$			
		P.C	).#:			
Cause:						
Solution:						
Millon.						
Date Comp	leted:		Approved:	,		
·			1 1			
	Time:	Service	Signature:			
		00,1100		KHEM		