

Outstanding Deficiencies

Caledon Club - Phase: 1B - Lot: 96B - Model: Glendale (38-05) Elev C 5 Bedroom

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date
07Nov23	IP PDI <i>Done</i>	5	BEDROOM #2- NOTE:~MISSIN DOOR STOP AT CLOSET DOOR. <i>Done</i>	ZANCOR CALEDON-SITE LABOUR 166742	Add	NoAppoint.
07Nov23	PDI	19	* FOYER/HALL- FLOORING~UNABLE TO REMOVE HEAT REGISTER AT FLOOR STUCK. <i>mud Rm.</i>	(ZANCOR) CALEDON-SITE LABOUR 166773	Add	NoAppoint.
07Nov23	PDI	20	* FOYER/HALL- STAIRS~DRYWALL REPAIR REQUIRED. RIGHT OF NOSING AT 2ND FLOOR <i>Fill sand/Paint next to tread drywall</i>	(ZANCOR) CALEDON-SITE LABOUR 166756	Add	NoAppoint.
07Nov23	PDI	27	* FOYER/HALL- STAIRS~SECURE TRIM AT BASEMENT LANDING <i>oak shoe trim install - ZAN</i>	VIA Trim and Doors Inc. 166763	Add	NoAppoint.
07Nov23	IP PDI <i>Done</i>	29	BASEMENT- STAIRS~SQUEAK AT FIRST TREAD AT STAIRS TO MAIN FLOOR FROM BASEMENT. <i>Done</i>	ZANCOR CALEDON-SITE LABOUR 166765	Add	NoAppoint.
07Nov23	IP PDI <i>Done</i>	33	BASEMENT- NOTE:~CENTRAL VAC COVER NOT INSTALLED. <i>Done</i>	ZANCOR CALEDON-SITE LABOUR 166774	Add	NoAppoint.
07Nov23	PDI	34	* BASEMENT- NOTE:~INSTALL STANDARD BATHROOM ACCESSORIES THROUGHOUT- SEE PHOTOS	(ZANCOR) CALEDON-SITE LABOUR 166768	Add	NoAppoint.
07Nov23	PDI	35	* BASEMENT- NOTE:~SCREEN NOT INSTALLED AT BEDROOM WINDOW. <i>Its in place but needs to be installed</i>	(ZANCOR) CALEDON-SITE LABOUR 166769	Add	NoAppoint.
07Nov23	PDI	37	* BASEMENT- NOTE:~ADJUST DOOR TO BEDROOM <i>Service cut door ribs rough</i>	VIA Trim and Doors Inc. 166776	Add	NoAppoint.
07Nov23	IP PDI <i>Done</i>	39	BASEMENT- NOTE:~HOOD FAN NOT VENTED OUT. <i>NA. Done by Homeowner</i> <i>Adjust closet base of bedroom door</i>	ZANCOR CALEDON-SITE LABOUR 166777	Add	NoAppoint.