Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 222W

<u>Date</u> Reported	<u> Type</u>	Number	Deficiency Description	<u>Trade</u> <u>Assigned</u>	Add Trade	<u>Appointment</u> <u>Date</u>	Item Completed	Initial
01Feb24	CONCILIATION	1	Stairs- General- Need finishing and stain/polish-SAND DOWN 2ND TREAD AT STAIRS FROM MAIN TO 2ND FLOOR SO STAIN WILL MATCH	Bolton Railings Inc. 172335	Add	<u>05Feb24</u>		/
01Feb24	CONCILIATION	2	Stairs- General- Gap in the stair- GAP AT NOSING AND POST AT LANDING TO 2ND FLOOR AT FLOOR LINE	Bolton Railings Inc. 172336	Add	<u>05Feb24</u>		Down
01Feb24	CONCILIATION	3	Stairs- General- s Crack/Gap between stairs and baseboard towards basement- gap at trim left side at stairs to mudroom	WYECROFT TRIM 172337	<u>Add</u>	<u>05Feb24</u>	<u> </u>	\ <u>\</u>
01Feb24	CONCILIATION	16	Stairs- General- Stairs post has very sharp edges - H.O Requesting sand edge of newel post at post infront of master bedroom sharp	Bolton Railings Inc. 172350	Add	<u>05Feb24</u>		BN
01Feb24	CONCILIATION	17	Dining Room- General- Need finishing - nail pop	Zancor - Innisfil Warranty Service 172351	Add	<u>05Feb24</u>		M
01Feb24	CONCILIATION	26	Exterior- General- House exterior wall has inconsistent bricks colour/type, layout patterns, missing grout fillings	River Valley Masonry Group LTD 172360	Add	<u>05Feb24</u>		
01Feb24	CONCILIATION	27	Exterior- General- Broken/ chipped off bricks on the porch pillar wallS- LEFT AND RIGHT SIDE PILLARS	River Valley Masonry Group LTD 172361	<u>Add</u>	<u>05Feb24</u>		
01Feb24	CONCILIATION	29	Exterior- General- Porch frame is not finished, uneven-	Promark Aluminum LTD. 172363	Add	<u>05Feb24</u>	painting	
<u>02Feb24</u>	Interval	16	Stairs- General- stain touch up required	Perfect Touch Painting 172466	<u>Add</u>	NoAppoint.		

Homeowner Signature:
The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.
Date:
Zancor Service Technician: