QN.

ANCOR Zancor Homes (Wasaga River) Ltd.
Warranty Services
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: Address:

Location: Today's Date: Contact(s): 3 Del Ray Crescent
Wasaga, Ontario L3Z 0T4
Rivers Edge - Phase: 1 - Lot: 280
22Feb24
Aiyaz Ahmed - Cell: (647) 761-2274 - (onetrader@hotmail.ca)
Nafeesa Tarrum -: (647) 761-2274 - (onetrader@hotmail.com)

Email: onetrader@hotmail.ca

Company:
Attention:
Telephone: Wasaga Zancor Site Labour Site Super. (705) 428-6483 (705) 428-6484

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
167694	PDI Seasonal	Exterior- General- touch up paint at front door frames and rear	05Mar24 /am	Bre

Date Completed: MAR 0 12

Homeowner Signature: , ,
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Signature:

Print Name:

T. Floa

Trade &/or Service Tech.

Date Completed:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Outstanding Deficiencies Rivers Edge - Phase: 1 - Lot: 280

Reported	Type	Number	Deficiency Description		Add	Add Appointment	Item	T-GG-1
			Exterior Council 1	1	Trade	Date	Completed	TRIMBIT
21Nov23	PDI	00	porch slab and stone at front and brick	Medi Group 167693	Add	05Mar24	×	and dependent of the second of
21Nov23	PDI	9	Exterior- General- touch up paint at front door frames and rear	Wasaga Zancor Site Labour 167694	Add	05Mar24	<	N
02Jan24	Interval	1	Stairs- General- stain touch up required due to minor bolton repair - newel post at left side and plug at tread before 1st landing	Perfect Touch Painting 170159	Add	05Mar24	7	And in California and the Califo
31Jan24	30-Day	. 4	Master Bedroom- General- The water is not coming in the upstair washrooms	Nota Plumbing & Heating Inc. 172300	Add	05Mar24		\$
31Jan24	30-Day	10	Exterior- General- The front needs to be cleaned properly-POWER WASH	Medi Group 172306	Add	05Mar24	*	
31 Jan24	30-Day	23	Main Hall- General- Nail pointing out in the dining area from the floor. (Near Servery entrance) place white foam to make it visible for the guys to find it	First Canadian Hardwood 172319	Add	05Mar24		A CONTRACTOR
31Jan24	30-Дау	28	Stairs- General- The stairs leading to the basement has many problems. Please look at the images. The look is very unprofessional and trim has too many gaps all aroundSECURE TRIM TO RISER	WYBCROFI TRIM 172324	Add	05Mar24	disease.	did or a service
31.Jan.24	30-Day	29	Kitchen- General- The backyard door strip in the middle needs to be painted. Why is it showing natural wood when the door is white? - service inspected - wrong atrical installed - black required - NEWMAR DOESNT DO THIS - SVC TO PAINT BLACK	Wasaga Zancor Warranty Service 172325	Add	05Mat24	平平	

	_
	\mathbf{x}
	~
	\simeq
	===
	~
	ä
	-
	-<
	=
	0
	ma.
	ran.
	23
- 4	m i
	¥4
	7
	22
	-
	=
	CD.
1.6	

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: HAR.
Zancor Service Technician:

32

ANCOR Zancor Homes (Wasaga River) Ltd.

HOMES Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: Address:

Location:
Today's Date:
Contact(s):

14Dec23
9 Tran Street
Wasaga, Ontario
Rivers Edge - Phase: 1 - Lot: 236
22Feb24
Shajeetha Satchithananthan - Home: (416) 303-2352 - (shajeetha.satchi@gmail.com)
Gowtham Satkunarajah - Home: (647) 528-0942 - (gowtham28@gmail.com)
shajeetha.satchi@gmail.com

Email:

Wasaga Zancor Warranty Service

Company:
Attention:
Telephone:
Fax:

(705) 428-6483 (705) 428-6484

Exterior wall penetrations had gaps that should be sealed with an appropriate sealant or appropriate gasket to prevent moisture, pest and insect entry and to improve the thermal envelope(N.A WE DO NOT CAULK EXTERIOR LIGHTS)

CAMBRA CAMBRA	05Mar24 /am	Laundry Room- General- Thermal imaging indicated ceiling insulation thickness in less than current standards across the house(conduct infrared camera reading at laundry/2nd bedroom floor)	30-Дау	172650
Dane	05Mar24 /am	Stairs- General- Seams Visible interior trim on stairs greater than 2mM(AT SHOEMOLD)	30-Day	172649
00 Ze.	05Mar24 /am	Foyer- General- Interior Trim more than 2mm Visible(CAULK BASE OF TRIM AT FRONT DOOR FLOOER LINE RIGHT AND LEFT SIDE	30-Day	172648
GRADING	05Mar24 /am	Exterior- General- Waterproofing on the exterior not installed properly on the foundation. Damage and open seams were visible- FINAL GRADE	30-Day	172646
HI CRAPAL,	05Mar24 /am	Exterior- General- g The building had areas of neutral or negative drainage that will route runoff from precipitation toward the foundation as a result of backfill settlement(FINAL GRADE)	30-Day	172644
Dork.	/am	Some windows had inadeqaute clearance from the grade(WINDOW WELLS TO BE CONFIRMED AT FINAL GRADE)		

172669	172668	172666	172660	172659	172658	172657	172653	172651
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day
Foyer- General- Front Door does not have 3 point locking system.	Master Bedroom- General- Windows not cleaned and has silicone/glue residuE	Kitchen- General- Patio Doors centre wood is chipped	Kitchen- General- Wood floor Chipped(CHECK PDI)	Foyer-General-Front Foyer tile isn't up to the trim on both sides of the door- CAULK AT FLOOR LINE	Dining Room- General- Opening between dinning room and kitchen/living room baseboard damaged and dry not complete	Foyer- General- sealant around door window not clean at front door glass	Attic- General- The vapor barrier system installed in the basement is incomplete and compromised SVC SECURE TAPE	Attic- General- insulation visible in the attic was below the listed standards. The attic cellulose requires a depth of 15.9". Gaps and voids in the depth were visible at soffits SVC MEASURE
05Mar24 /am	05Mar24 /am	05Mar24 /am	05Mar24 /am	05Mar24 /am	05Mar24 /am	05Mar24 /am	05Mar24 /am	05Mar24 /am
Z/H	Day.		Dorg	Do Z	Dare	lone.	Dora	7/1

		TRIM		
		REPAIR SEAM AT		
1000		completed- SVC		
7		bedroom trim not		
•	/am	General- Master		
	05Mar24	Master Bedroom-	30-Day	172671
		YELLOW PATCH		
1020		dining room hallway-		
7		on the wall in the		
	/am	General- Missing Paint		
	05Mar24	Dining Room-	30-Day	172670
		SITE TO CONFIRM		
		point locking system-		
		size doors has a 3		
		which are the same		
		The back patio doors		

Date Completed:	
Marc	
5/2	
10	

Homeowner Signature: What Werbawsky
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Trade &/or Service Tech.

Date Completed:

Signature:

Print Name:

V

Morrey

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Outstanding Deficiencies Rivers Edge - Phase: 1 - Lot: 236

07Feb24	07Feb24	07Feb24	07Feb24	07Feb24	07Feb24	07Feb24	07Feb24	<u>07Feb24</u>	07Feb24	07Feb24	Date Reported
30-Day	30-Day	30-Day	30-Day	30-Дау	30-Day	30-Day	30-Дау	30-Дау	30-Day	30-Day	Type
15	17.	12	11	10	9	00	7	0	4	دي	Number
Stairs- General- Seams Visible interior trim on stairs greater than 2mM(AT SHOEMOLD)	Foyer- General- Interior Trim more than 2mm Visible(CAULK BASE OF TRIM AT FRONT DOOR FLOOER LINE RIGHT AND LEFT SIDE	Exterior- General- Waterproofing on the exterior not installed properly on the foundation. Darnage and open seams were visible- FINAL GRADE	Attic- General- Damaged H-clips and deteriorated plywood visible	Exterior- General- g The building had areas of neutral or negative drainage that will route runoff from precipitation toward the foundation as a result of backfill settlement(FINAL GRADE)	Exterior- General- Some windows had inadequate clearance from the grade(WINDOW WELLS TO BE CONFIRMED AT FINAL GRADE)	Exterior- General- Windows and Door Sealant missing in some areas(AT EXTERIOR FRONT DOOR TRIM FLOOR LINE RIGHT SIDE ONLY)	Exterior- General- The sill transitions at which the exterior wall-covering material terminated at a sidewall transition were loose and damaged	Exterior- General- Exterior wall penetrations had gaps that should be sealed with an appropriate sealant or appropriate gasket to prevent moisture, pest and insect entry and to improve the thermal envelope(N.A WE DO NOT CAULK EXTERIOR LIGHTS)	Exterior- General- Drip Edge missing on certain areas of the roof	Exterior- General- There were downspouts present that were discharging within 6 feet of the foundation of the building (FINAL GRADE/SPLASH PADS NOT COMPLETE)	Deficiency Description
Wasaga Zancor Warranty Service 172649	Wasaga Zancor Warranly Service 172648	Wasaga Zancor Warranty Service 172646	Kingsview Carpentry 172645	Wasaga Zancor Warranty Service 172644	Wasaga Zancor Warranty Service 172643	<u>Newmar</u> 172642	Medi Group 172641	Wasaga Zancor Wananty Service 172640	Trudel And Sons Roofing Ltd. 172638	Wasaga Zancor Warranty Service 172637	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	Add Appointment Trade <u>Date</u>
_	(2005	(4	~	8	(28	<	Item Completed
U E	J.	S. W.	DMM.	E)	JE JE	Jw		J. W.		JW	Initial

07Feb24 30	07Feb24 30	<u>07Feb24</u> 30	<u>07Feb24</u> 30	<u>07Feb24</u> 30	07Feb24 30	<u>07Feb24</u> 30	<u>07Feb24</u> 30	<u>07Feb24</u> 30	07Feb24 30	<u>07Feb24</u> 30	07Feb24 30	<u>07Feb24</u> 30	07Feb24 30	<u>07Feb24</u> 30	07Feb24 30	<u>07Feb24</u> 30
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Дау	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day
35 E	34	333	31	30	29 a	28 d	25	24 ii	23 b	22 d	21 L	20 lo	19 b	S H.'S A	17 st	16
Dining Room- General- Missing Paint on the wall in the dining room hallway-YELLOW PATCH	Foyer- General- Front Door does not have 3 point locking system. The back patio doors which are the same size doors has a 3 point locking system- SITB TO CONFIRM		Kitchen- General- Patio Doors centre wood is chipped	Kitchen- General- Under the sink cabinet base is darnaged.	Kitchen- General- Crown Moulding above the pantry, in the corner not completed correctly	Kitchen- General- Missing pullout drawer	Kitchen- General- Wood floor Chipped(CHECK PDI)	Royer- General- Front Foyer tile isn't up to the trim on both sides of the door- CAULK AT FLOOR LINE	Dining Room- General- Opening between dinning room and kitchen/living room baseboard damaged and dry not complete		Living Room- General- Living room ceiling drywall seams visiblE	Master Ensuite- General- Toilet is loose and wax ring providing a moisture seal is deformed	Master Ensuite- General- The bathfub was loose and unstable-secure MOVING	Attic- General- The vapor barrier system installed in the basement is incomplete and compromised SVC SECURE TAPE	E. B	thickness in less than current standards across the house(conduct infrared camera reading at laundry/2nd bedroom floor)
Wasaga Zancor Warranty Service 172670	Wasaga Zancor Wattanty Sctvice 172669	Wasaga Zancor Warranty Service 172668	Wasaga Zancor Warranty Service 172666	New Image Kitchens 172665	New Image Kitchens 172664	New Image Kitchens 172663	Wasaga Zancor Warranty Service 172660	Wasaga Zancor Wasianty Service 172659	Wasaga Zancor Warranty Service 172658	Wasaga Zancor Warranty Service 172657	Foremont Drywall 172656	Nota Plumbing & Heating Inc. 172655	Nota Plumbing & Heating Inc. 172654	Wasaga Zancox Warranty Service 172653	<u>Wasaga Zancor</u> Warranty Service 172651	Wasaga Zancor Warranty Service 172650
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add
05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24	05Mar24
		<	Ph.	¥	*	æ	<		(R	2	<		0 7
J.W	S. W.	J.W					Jw	JW	Jw			and the second		J.W	Jw	

s/ZanHSReportDeficiencyCheckList.php?&var 2/3

Deficiency Check List - User: Alexandria Damianidis

MD	(No.Agraint	Add	Weatherstripping Ltd 173158	Exterior- General- caulking required	œ	Interval	22Feb24
Jw	<	05Mar24	Add		Master Bedroom- General- Master Wassaga Zancor bedroom trim not completed- SVC Warranty Service REPAIR SEAM AT TRIM 172671	36	30-Day	07Feb24

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Mar 5/24
Zancor Service Technician: