

Outstanding Deficiencies

Caledon Club - Phase: 1B - Lot: Block 181 - Unit 8

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
22Mar24	PDI	1	POWDER ROOM- NOTE:-HOMEOWNER REQUESTING TO HAVE GROUT CLEANED AT TUB	ZANCOR CALEDON-SITE LABOUR 174509	Add	08Apr24		
22Mar24	PDI	2	POWDER ROOM- FLOORING-REPLACED DAMAGE TILE RIGHT SIDE ENTRANCE TO POWER AT T MOLD	AV Classic 174510	Add	NoAppointment.	Done.	L
22Mar24	PDI	3	FOYER/HALL- NOTE:-DENT ON STIPPLE AT OFFICE CEILING ENTRANCE	Foremont Drywall 174511	Add	NoAppointment.		
22Mar24	PDI	4	KITCHEN- WINDOWS-DENT ON BOTTOM TRACK BELOW OPERATING DOOR AT FLOOR LINE.	Newmar 174512	Add	NoAppointment.		
22Mar24	PDI	7	MASTER BEDROOM- WALLS-LINE IN STIPPLE AT PEAK LEFT SIDE	Foremont Drywall 174515	Add	NoAppointment.		

Homeowner Signature: _____

The Homeowner acknowledges and accepts that all
initialised work has been completed in a workman like
manner to their satisfaction.

Date: _____

Zancor Service Technician: B. S. S. S. S. S.