

Suite 707 we
scan to pass.

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: ALFONSO CAMAIONI SUITE # 707

DEVELOPMENT NAME: eve ADDRESS: 3515 KARIYA

RES. TEL: _____ BUS. TEL: _____ CELL: 416 708 3364

FAX: _____ EMAIL: _____

DATE OF REQUEST: 05-05-09

SERVICE REQUEST:

- ✓ 1. CABINET DRAWER NOT SCREWED IN LEFT OF FRIDGE.
2. IN KITCHEN
- ✓ 3. MIRROR IN FRONT ENTRANCE DAMAGED BOTTOM RIGHT
- ✓ 4. MIRROR IN MASTER BEDROOM IS BROKEN MOULDING.
5. COMING APART
- ✓ 6. IN SECOND BEDROOM NO SCREEN DOOR

7. _____

8. _____

9. _____

10. THANKS MARK

AUTHORIZE Suite Entry

Alfonso Camaioni

RECEIVED APRIL 13/09 9:00 AM
Suite 707 live
Scan to pass

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: ALFONSO CAMAIONI SUITE # 707

DEVELOPMENT NAME: one ADDRESS: 3515 KARIYA DR

RES. TEL: 416 708 3304 BUS. TEL: — CELL: 4-708-3304

FAX: — EMAIL: —

DATE OF REQUEST: APRIL 13-2009

SERVICE REQUEST:

1. No Screen in Second bedroom
2. GLASS IS DEFECTED IN THE ENTRANCE CLOSED DOOR (BOTTOM RIGHT)
3. Light fixture in main washroom Defected
4. fan in MAIN & MASTER WASHROOM, KNOCKING NOISE
5. WHEN TURNED ON
6. SCREW MISSING IN KITCHEN DRAWER 3RD DRAWER LEFT OF FRIDGE
7. —
8. PLEASE CALL 24 HOURS BEFORE ENTERING
9. THANKS 416 708-3304 ALFONSO
10. —