

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

OR (905) 882-4636

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: George Andropoulos SUITE # 205

DEVELOPMENT NAME: Amacoon ADDRESS: 3515 Kariya Drive


RES. TEL: 416-805-9153 BUS. TEL: _____ CELL: 416-805-9153

FAX: _____ EMAIL: _____

DATE OF REQUEST: June - 06 - 09

SERVICE REQUEST:

1. The Hardwood floor need to be repaired
2. before it becomes worse. The floor is lifting
3. up from the ground. Please call my cell
4. ASAP to discuss this matter. Thank you.
5. _____
6. _____
7. _____
8. I am giving you Authority to view or fix the
9. matter but please call or knock.
10. _____



AMACON DEVELOPMENT**AMACON SERVICE REQUEST FORM**

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5V 1A1

TEL: 416-593-9069 FAX: 416-593-9068

OR (905) 882-4686

ATTENTION: CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2009 FAX: 905-848-7827

NAME George Andreopoulos SUITE # 205DEVELOPMENT NAME Five ADDRESS 3515 Kariya Dr.HSTEL: 416-805-9153 HSTEL: _____ CELL: 416-805-9153FAX: _____ EMAIL: gandreopoulos@five.comDATE OF REQUEST: May -26- 2009

SERVICE REQUEST:

1. Hardwood floor lifting up and is damaged from incorrect install
2. Need this addressed ASAP.
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____