

SEP 09 2010

AMACON DEVELOPMENT**AMACON SERVICE REQUEST FORM**

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: CHUNG YAN TSESUITE # 2807

DEVELOPMENT NAME: _____

ADDRESS: 3515 KARIYA DRIVE

RES. TEL: _____

BUS. TEL: _____

CELL: 647-300-6088

FAX: _____

EMAIL: _____

DATE OF REQUEST: 8 SEP, 2010

SERVICE REQUEST:

1. All power outlets are no power in master bed room
2. All power outlets are no power in bed room
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____

Tested Brookers Reser and still no power

Tested Bedroom Arch Fast Reser Brooker - Suspect Breaker