

Page

I authorized you to
come into 705 to
Fix the problems
G. Boothe

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J 1A1

TEL: 416-363-9000 FAX: 416-363-9000
(605) 282-4636

905-232-4637 (Fax to Amaccon)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: MISS KARIYA DE

TEL: 905-232-2000 FAX: 905-232-2000

URGENT

NAME: G. Boothe

705

DEVELOPMENT NAME

ADDRESS: 3515 Kariya Dr

RETEL: 416-906-6449

BUSTEL:

CELL:

FAX:

EMAIL:

DATE OF REQUEST: March 17, 2010

SERVICE REQUEST:

Very important. For some one to
find washroom toilet went blank
it's dirty

This is 4th.
Request to Fix
#705 Problem

1. Dated the has been requested to Fix Mould in
2. all windows in kitchen. The ceiling that
3. started to leak on January 4, 2010 and now
4. moulding and turning black. I gave a
5. request for leaking of ceiling on Jan. 4, 2010
6. someone came to take a look at the
7. ceiling the next morning and said they
8. would come back after lunch, and
9. until now March 17, 2010 they hasn't come
10. back for the ceiling. On February 9, 2010
Dec, 30, 2009: and November 23, 2009

PFO

I am authorized for you to come in
Gibbooth

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 1A2

TEL: 905-232-4637 FAX: 905-232-4637 905-232-4637 (FAX TO AMACON)
ATTENTION CUSTOMER CARE: 3515 KARIYA DR. CUSTOMER CARE

TEL: 905-232-2000 FAX: 905-232-2027

NAME: Gibbooth

DEVELOPMENT NAME: _____ SITE: 705

RE: TEL: _____ ADDRESS: 3515 Kariya Dr

FAX: _____ CELL: _____

DATE OF REQUEST: Jan 4/10

SERVICE REQUEST:

1. Kitchen ceiling worker is coming down Gibbooth
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____

I give authorized for you
in my absent
Gibbooth
705

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 2E1

TEL: 416-363-5063 FAX: 416-363-5065 905-232-4637 (Fax to AMACON)
905-232-4636 CUSTOMER CARE
ATTENTION CUSTOMER CARE: 3515 KARYA DR.

TEL: 905-343-3063 FAX: 905-343-2827

NAME: Gifford Boothe DATE: 705

DEVELOPMENT NAME: ADDRESS: 3515 Karyia DR

RES TEL: 416-906-6449 BUS TEL: USB-OCI V
CELL:

FAX: EMAIL:

DATE OF REQUEST: November 23, 2009

SERVICE REQUEST:

1. mould spots in Kitchen + Bedrooms
2. glass doors + windows Bottom + middle
3. part of glass windows
4. Could some one come and
5. do something about fixing for me
6. Thank
7. G. Boothe
8. NOV, 23, 2009
- 9.
- 10.

I authorized for me
G. Boothe

First Request was
Late November 2009
came in early Dec 09
AMACON DEVELOPMENT

give instructions on 10
Enter
G. boethe

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUMMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5H 1A1

TEL: 416-593-0889 FAX: 416-593-0889
OR (416) 593-4636

905-232-4437 (For Amacn)
CUSTOMER CARE

ATTENTION: CUSTOMER CARE: JESS KANYA DE

TEL: 905-445-2023 FAX: 905-445-2027

NAME: G. boethe

705

DEVELOPMENT NAME:

SUITE #

NOTE:

BIRTH:

ADDRESS:

FAX:

EMAIL:

CELL:

416-906-6469

DATE OF REQUEST:

December 30, 2009

To complete

SERVICE REQUEST:

(Second Request)

RECEIVED
DEC 30 2009

1. 2nd Request for mould fixing in
2. December 10, workers did portion of
3. Fixing mould in kitchen windows
4. and Bedroom. they say that they
5. would come back and change
6. Bedroom glass and. But paint the
7. Kitchen window
8. and no sign of them also
9. to clean the blind that was moulded
10. by the moulding of the window that in
11. the Kitchen. also could you also fix
12. the closet door also on the front