

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5V 1A2

TEL: 416-363-0000 FAX: 416-363-0005 905-232-4637 (Formerly Amecor)
905-232-4626 CUSTOMER CARE

ATTENTION CUSTOMER CARE 2515 KENNEDY RD.

TEL: 905-232-2000 FAX: 905-232-2027

NAME: Leoncio Pineda

DEVELOPMENT NAME: EVE SUITE: 606

ADDRESS:

RETEL: RETEL: CELL:

FAX: EMAIL:

DATE OF REQUEST: July 21, 2010

SERVICE REQUEST:

1. We received a note from Customer Care
2. That the probable cause of the
3. popping out of the floor is more likely
4. due to aircon not having it (on)
5. Is it our fault of not having
6. aircon for the past few weeks?
7. I do hope you will look
8. into this matter.
- 9.
- 10.

Out of warranty. Thank you

Mr. Leo Pineda

Gahme,
who
informed
them?
Porvi