

RECEIVED

DEC 23 2010

AMACON DEVELOPMENT**AMACON SERVICE REQUEST FORM**

EVC 309

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2889 FAX: 905-848-2827
(905) 832-4636 (416) 369-9068NAME: Olha TytsyakSUITE # 309

DEVELOPMENT NAME: _____ ADDRESS: _____

home RES. TEL: (905) 756-4022 BUS. TEL: _____ CELL: (647) 833-2912FAX: _____ EMAIL: olha.tytsyak@gmail.comDATE OF REQUEST: December 18, 2010

SERVICE REQUEST:

1. Both windows - the one in the living room & in the
2. bedroom - are constantly dripping
3. The water condenses and is leaking causing
4. the window sill to swell as well as the walls to
5. be wet
6. Please advise if this issue can be fixed at
7. your earliest. Thank you
8. _____
9. Please call before entering. However,
10. if noone answers smo can go in