

Peel Standard Condominium Corporation No. 889

## Suite Performance Resident / Owner Questionnaire

have retained Belanger of 1912 The Board of Director's and Property Managers of your Condominium Corporation have retained Belanger Engineering to assess the condition of the common elements at this development. Your assistance in answering this questionnaire is needed to establish the extent and nature of any suite and any development performance related problems that should have been resolved to date. So please take some time to observe, and recall, what is or has happened in your suite during various weather conditions.

In order for us to include any performance related problems of the common elements in the second year warranty claim, please complete this questionnaire and return it to your condominium manager, Ms. Danielle Casha, in the management office by Tuesday Sentember 25, 2012. Additional of

your balcony/terrace (if applicable), parking garage, etc., may be made on the back of this questionnaire.
Name: Said AL-Neddaff Address: 3525 Cariya Dr. Miss. # 1005  ON. L5B OCL  Suite Number: 1005
1. Have there been repairs completed on the exterior and/or interior of your suite? Yes No If so, please describe the nature and extent of repairs carried out.
Water Leaking from aircondetioning Duct
2a) Does water leak into your suite?  If so, which room(s) and at what level (floor, ceiling, or around windows)?  Yes No
Water Leak was from the aircoclition duct to the bedroom Carpet b) Approximately, when was the last date water leaked into your suite?
It Was in Aug: 2012
c) Does water leakage occur shortly after periods of rain or on warm, sunny days in the winter or spring? The Leaking Was in Augustand during Sunny days.  Canol the Source of leaking water (Continue in the back)
3. Do you have black mildew on your ceilings or walls?  If so, where?  Yes No

Thank you for your participation.