**HEATHWOOD** 

**Heathwood Homes (Whitby) Limited** 

245 Yorkland Blvd., Suite 100 Toronto, Ontario

M2J 4W9

Ph: (416) 490-1400 Fax: (416) 490-1401 **Purchase Order** 

PO# DE-TR-7-733-34798 Vendor PO: DE-TR-7-733-34798

Created: 21Jul25 Created By: Bei Liu

Approved By: Sheldon Alspector

Required Date: 21Jul25

Vendor Ship To

Stone Edge Marble & Granite Inc. 1640 Sismet Road Mississauga, Ontario

L4W 1R4

Ph: (905) 625-7866 Fax: (905) 624-3050 Reference

Re: Lot 733 Phase 7

Model: 39-3573 A The Cedarvale

Site: Country Lane

Quantity	Account	Description	Unit Price	Ext. Price
1.00	0704	FOR LAUNDRY SINK SEE SPECS - GRANITE - GRANITE CUTOUT WITH STRAIGHT EDGE POLISH TO ACCOMMODATE UNDER MOUNT KITCHEN/LAUNDRY SINK -	\$200.00	\$200.00
1.00	0704	GRANITE - SERVERY BAR SINK CUTOUT/POLISH - SEE SPECS - PLUMBING - BAR SINK - COMPLETE BAR SINK FOR SERVERY INCLUDES PLUMBING ROUGH-IN AND MOEN ALIGN BAR PREP FAUCET (MODEL: 5965) AND BOSCO UNDERMOUNT SINK (MODEL 207029)	\$200.00	\$200.00
21.25	0704	LAUNDRY ROOM - GRANITE - ADDITIONAL COUNTERTOP PER SQ.FT UPGRADE 3 - GRANITE-see upgraded single hole faucet and undermount sink	\$65.00	\$1,381.25
1.00	0704	- GRANITE - ENSUITE BED 2 - GROUP 1 WITH 1 1/2 IN MITER EDGE - UPG - CABINETRY-delete std countertop: GRANITE-see upgraded single hole faucet and undermount sink	\$830.00	\$830.00
1.00	0704	- GRANITE - LOWER BATH - GROUP 2 WITH 1 1/2 IN MITER EDGE - UPG - CABINETRY-delete std countertop: GRANITE-see upgraded single hole faucet and undermount sink	\$754.00	\$754.00
1.00	0704	- GRANITE - MAIN BATH - GROUP 2 WITH 1 1/2 IN MITER EDGE - UPG - CABINETRY-delete std countertop: GRANITE-see upgraded single hole faucet and undermount sink	\$1,188.00	\$1,188.00
1.00	0704	- GRANITE - PRINCIPAL ENSUITE - GROUP 1 WITH 1 1/2 IN MITER EDGE - UPG -	\$1,600.00	\$1,600.00
1.00	0704	- GRANITE - KITCHEN - GROUP 4 WITH 1 1/2 IN MITER EDGE - UPG -	\$1,896.00	\$1,896.00

\$8,049.25 Total:

## Notes

- All above amounts are net of taxes.

- All invoices must quote a PO# and delivery address.
  All deliveries must be authorized by the site superintendent.
  All materials and/or work must comply with all applicable building codes and regulations.