Purchase Order



3550 Langstaff Road, Suite 200 Woodbridge, Ontario L4L 9G3 Tel (905) 856-2150 / (416) 213-7181 Fax (905) 856-6543

Purchase Order #: 39437

Date Printed: 24-Jun-20

To: Appliance Canada

Lot: 712 - Braylea Investments Inc. - SHELTER ISLAND Phase: 1

Item	Description	Qty.	Unit Price Ext. Price
1 -	KITCHEN- Install UPG built in Mmicrowave in the base cabinet of	1	\$474.00
K828.	kitchen with Trim Kit, as per the kicthen layout. Install the Panasonic		
	Microwave Model # ST765S, cost inclusive of Trim Kit and install. See		
	specs.		
2 -	KITCHEN- Install UPGRADE stainless steel chimney hood fan	1	\$624.00
K0021.	"FALMEC VULCANO" in lieu of standard combination micro/hood fan in		
	Upgrade package 1. See attached specs.		
3 -	APPLIANCE PACKAGE - INSTALL 1ST UPGRADE APPLIANCE	1	\$4,055.00
A0033.	PACKAGE WITH 33 IN FRIDGE in lieu of standard package.		
	NOTE: DELETE - Do NOT install the standard OTR micro included in the		
	Upg #1 package.		

\$5,153.00

Please NOTE: INVENTORY UNIT - SEE SITE SUPER FOR DELIVERY DATES

The Subcontractor agrees to perform the Work and to supply the Extras as may be ordered by the Contractor within the one year period from the date hereof and the price of the Work per dwelling unit listed in pre-determined contract pricing, and the price of each Extra set forth in said contract pricing, which prices are firm and guaranteed from such one year period and are inclusive of all taxes now or herein after imposed whether federal, provincial or municipal, including without limitation all goods and services taxes.

The Subcontractor prior to commencement of the Work with respect to each dwelling unit shall visit the Site-Office and check the specifications, pertaining to each such dwelling unit to ascertain if there are any "changes" or "extras" with respect to such dwelling unit that will effect his Work. If he fails to do this, or if he overlooks any item on the specification that affects his Work it will be his responsibility to rectify his Work and to bear the cost of rectification resulting from his oversight.

For any work orders issued for which there is no conract price subcontractor is to obtain a purchase order from Head Office.

Invoices pertaining to this Purchase Order MUST be Invoiced To: Braylea Investments Inc.

WorkOrderSQL.rpt 23jun09 Page 1 of 1
24-Jun-20