

210-1455 Youville Drive Orleans, On K1C 6Z7 Phone: 613-837-1104

Vendor:

FIREPLACE CENTER & PATIO SHOP 1722 CARLING AVENUE OTTAWA, ON K2A1C7

Ship To:

Site:

**RATHWELL LANDING** 

Lot/Unit: Model:

**LOT 257** 1020 STANDARD

Civic:

724 PARADE DRIVE

tel:

6137281775

fax: contact:

ORDER DATE Dec 21, 2020	CHG. ORDER DT.	CANCEL DATE	RESPONSIBILITY ARIEL	VENDOR # F10	TERMS NET 30 DAYS
Comments/Special In	REFERENCE				
		· · · · · · · · · · · · · · · · · · ·			

JOB/LOT/COST	REFERENCE	Description	QTY ORDERED	UNIT PRICE	EXTENSION
056-257-666	CODE 666	REPLACE DAMAGE CAP AT GAS FIREPLACE IN GREAT ROOM	1.0000	175.000000	175.00
			Subtotal		175.00
					22.75
Authorized Signature			Total Order Value		197.75

ORDER TERMS AND CONDITIONS

1. INVOICES must bear exact same prices and terms or authorization for changes must be received from our company in writing prior to shipping.
2. The right is reserved to cancel all or part of this order if not delivered within the time specified.
3. Packing slips must accompany all shipments.
4. In the event of interruption of our business in whole or in part by reason of fire, flood, windstorm, earthquake, war, strike, embargo, acts of God, governmental action, or any causes beyond our strategy and other parties of cancelling and private in whole or in part.

control, we shall have the option of cancelling undelivered orders in whole or in part.

5. Acceptance of this pirchase order, or shipment of it will constitute an agreement to all of its specifications as to terms, delivery and prices.

6. No deliveries accepted after 4:00 pm or on weekends.

## **Purchase Orders**

From:

lan Kolesnik

Sent:

Thursday, December 10, 2020 10:37 AM

To:

Leslie Emmerson

Cc:

Purchase Orders; Ipelicos@fireplacecenter.com

Subject:

Re: Lot 257--Damaged Cap

Ariel,

Site damage to the cap was caused by unknown so no back charges.

Thanks,

lan

On Dec 10, 2020, at 10:33 AM, Leslie Emmerson < leslieemmerson@fireplacecenter.com > wrote:

HI lan,

I am sending from Webmail as our email is done

the Cost to Replace the damaged cap is \$175.00+HST. as we talked about we will do this Jan 5th 2021

Ariel please send PO

Thanks Leslie