210-1455 Youville Drive Ottawa, On K1C 6Z7 Phone: 613-837-1104

Vendor:

MIRROR WORKS INC. 2713 FENTON ROAD OTTAWA, ONTARIO K1T 3T8 Ship To:

Site:

PLACE ST. THOMAS PHASE 7

Lot/Unit:

LOT 3

Model: Civic:

1015 REVERSED

886 COLOGNE STREET

tel:

613-746-4245

fax:

contact:

ORDER DATE Nov 21, 2023	CHG. ORDER DT.	CANCEL DATE	RESPONSIBILITY ARIEL	VENDOR # M03	TERMS NET 30 DAYS
Comments/Special In	REFERENCE				

JOB/LOT/COST	REFERENCE	Description	QTY ORDERED	UNIT PRIC	CE EXTENSION
067-003-666	CODE 666	SUPPLY MIRROR 48" x 36 BEVELLED ENSUITE BATHROOM -	1.0000	142,1200	142.12
	1	Subtotal		142.12	
for	1	нѕт		18.48	
Authorized Signature				r Value	160.60

ORDER TERMS AND CONDITIONS

- 1. INVOICES must bear exact same prices and terms or authorization for changes must be received from our company in writing prior to shipping.

- The right is reserved to cancel all or part of this order if not delivered within the time specified.
 Packing slips must accompany all shipments.
 In the event of interruption of our business in whole or in part by reason of fire, flood, windstorm, earthquake, war, strike, embargo, acts of God, governmental action, or any causes beyond our control, we shall have the option of cancelling undelivered orders in whole or in part.

 5. Acceptance of this pirchase order, or shipment of it will constitute an agreement to all of its specifications as to terms, delivery and prices.
- 6. No deliveries accepted after 4:00 pm or on weekends.

Purchase Orders

From:

Justin Stoll

Sent:

Tuesday, November 21, 2023 2:38 PM

To:

Purchase Orders

Subject:

Fwd: Mirror replacement lot 3 ensuite

Justin Stoll

Site Supervisor Valecraft 2019 Embrun 613-809-2654

Begin forwarded message:

From: Justin Stoll <jstoll@valecraft.com>
Date: November 21, 2023 at 1:23:14 PM EST
To: Tanis Blair <tanis@mirrorworks.com>
Subject: Mirror replacement lot 3 ensuite

Hi Tanis,

I will need the mirror replaced in lot 3 ensuite. Can this be done ASAP as the home closes Dec 4. Ensuite mirror 48x36 #142.12

-Ariel, please send a po for this. Looks like cleaners scratched it when removing stickers. No way to prove this though

Justin Stoll

Site Supervisor Valecraft 2019 Embrun 613-809-2654