


Outstanding Deficiencies

The Village at Kings Ridge - Phase: 1 - Lot: Block 2 Unit 11

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
<u>17May21</u>	PDI	1	Main Bathroom- General-FRONT OF SIDESPLASH IS CRACKED	QTK 143811	Add	<u>18Jun21</u>	☒	
<u>17May21</u>	PDI	3	Kitchen- General-MISSING PIECE OF VALANCE-RIGHT OF STOVE	QTK 143813	Add	<u>18Jun21</u>	☒	
<u>17May21</u>	PDI	4	Kitchen- General- UPPER SHELVES TO THE RIGHT OF STOVE NOT LEVEL	QTK 143814	Add	<u>18Jun21</u>	☒	
<u>17May21</u>	PDI	7	Family Room- General-HRV NOT WIRED TO TSTAT	Downsview Heating & Air Cond. 143817	Add	<u>No Appointment</u>	☐	
<u>17May21</u>	PDI	8	Basement- General- PAINT STAIRS AND LEAVE TOUCH UP QUARTS	Princeton Painting 143818	Add	<u>No Appointment</u>	☒	
<u>17May21</u>	PDI	9	Exterior- General- LEFT GARAGE DOOR-- MIDDLE PANEL DAMAGED AND INSTALL BOTH HANDLES	Royal Overhead Doors 143819	Add	<u>No Appointment</u>	☒	

NEWMA WINDOW SCREEN TO
INSTALL

Downsview- HRV Missing a PART -
IN ORDER

Homeowner Signature: 

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: JUNE 18/21

Zancor Service Technician: LOU MEN