

Boomer - Thursday July 8th & 9th.

Outstanding Deficiencies

Belle Aire Shores - Phase: 1 - Lot: 7

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
04Jan21	Interval	4	Other- General- ADJUST GMD	Newmar 141907	Add	08Jul21	✓	go.
09Mar21	30-Day	1	Kitchen- General- Granite counters are not the same depth on either side of the stove	Redstone Marble 142900	Add	08Jul21	✓	go.
09Mar21	30-Day	4	Foyer- General- Front door extremely hard to close. Does not close without forcing door shut--as per h/o, Newmar will replace the front door	Newmar 142903	Add	08Jul21		
09Mar21	30-Day	5	Garage- General- Passage door garage to house, difficult opening handle	WYECROFT TRIM 142904	Add	08Jul21	✓	go
09Mar21	30-Day	13	Kitchen- General- Kitchen island corner has white haze on it FROM PDI BOOKED FOR MARCH 5TH	New Image Kitchens 142912	Add	08Jul21		
09Mar21	30-Day	17	Other- General- Loft floor - issue with floor squeaking loudly - builder looking into issue as is same in other models	Zancor - Inisfill Warranty Service 142916	Add	08Jul21	<i>Homeowner will monitor</i>	go
09Mar21	30-Day	17	Other- General- Loft floor - issue with floor squeaking loudly - builder looking into issue as is same in other models	Kingsview Carpentry 142921		08Jul21		
09Mar21	30-Day	18	Family Room- General- Sloped ceiling noted issue with drywall seams on smooth ceiling during pdi for closing(Family and Dining)	Foremont Drywall 142917	Add	08Jul21	✓	go
15Jun21	Interval	8	Exterior- General- DECORATIVE TRIM OVER LEFT GARAGE DOOR NOT THE SAME AT RIGHT SIDE	Newmar 144732	Add	No Appointment		

Homeowner Signature: *[Signature]*

Boomer

*Scanned July 13
Removed July 13
go*