

Wednesday July 6
@ 1-2pm

Outstanding Deficiencies

Reserve Of Country Trails - Phase: 1 - Lot: 19

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
05Apr22	PDI	11	EXTERIOR- --EXTERIOR PAINTING NOT COMPLETE	Princeton Painting 147234	Add	07Jul22		
05Apr22	PDI	13	EXTERIOR- PORCH-CHIP ON FRONT PORCH AT EDGE TO STAIRS	Toronto Concrete & Drain 147225	Add	07Jul22		
25May22	30-Day	4	Master Ensuite- General- Shower head dripping water	Nota Plumbing & Heating Inc. 147943	Add	07Jul22		
25May22	30-Day	8	Exterior- General- Cracked stone left of left garage door above foundation	Medi Group 147947	Add	07Jul22		
02Jun22	Interval	5	Exterior- General- wrong HRV Vent installed	Downsview Heating & Air Cond. 147988	Add	07Jul22		
29Jun22	Interval	6	Kitchen- General- Inspect countertop as per h.o Rough	Zancor - Brampton Warranty Service 148430	Add	07Jul22	✓	HP
29Jun22	Interval	7	Master Ensuite- General- Adjust shower glass door hitting fixed glass	Metropolitan 148431	Add	07Jul22		
29Jun22	Interval	8	Master Ensuite- General- Inspect shower drain-As per h.o loose cement - silicone if required	Zancor - Brampton Warranty Service 148432	Add	07Jul22	✓	HP
29Jun22	Interval	9	Kitchen- General- wrong paint used for touch ups in kitchen	Zancor - Brampton Warranty Service 148433	Add	07Jul22		

Homeowner Signature: X HP

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: July 6/22Zancor Service Technician: KOMPEN