

Outstanding Deficiencies Parsons Precast INC.

Work Order Date	Lot	Phase	Site	Type DAI	Deficiency Description	Address	Contact	Appointment Date	Days Out
14Jul22	8A ✓	✓	Caledon Club	PDI 148837	EXTERIOR-PORCH-CHIP ON BOTTOM STEP FRONT PORCH STEPS	As per site B7	Christine Huyhn - Work: (647) 409-0713 Ali Erol - Cell: (647) 408-1585	No Appoint.	55
12Aug22	21A ✓	✓	Caledon Club	PDI 149383	Exterior-NOTE:-CHIP AT FIRST STEP	As per site B7	Gaurav V. Patel - Home: (647) 401-8200 Gayatriben R. Patel - Cell: (647) 627-6790	No Appoint.	26
27Jul22	22A ✓	✓	Caledon Club	PDI 149120	EXTERIOR-PORCH-CHIP ON FIRST TREAD	As per site B7	Gloria E. Holder - Cell: (647) 401-0796 Sherville Holder - (289) 242-2921	No Appoint.	42
14Jul22	10 ✓	✓	Reserve Of Country Trails	30-Day 148866	Exterior- item 26- outdoor entrance stairs damage	As per site B7	2ND H.O RANDEEP BASSI - Home: (647) 774-7777 - Cell: (647) 774-7777	02Aug22	55

~~10A Caledon~~

Caledon Club - Mayfield Rd + McLaughlin Rd
Brampton.

Reserve of
Country Trails - Mountainash Rd + Countryside Drive.

Sept 9th - patched chips Lot 21A
bottom riser 22A
(site damage) 8A

#

(May have a porch problem)

Self

6 Rainbrook class