

Outstanding Deficiencies Parsons Precast INC.

Work Order Date	Lot	Phase	Site	Type DAI	Deficiency Description	Address	Contact	Appointment Date	Days Out
14Jul22	8A ✓	1	Caledon Club	PDI 148837	EXTERIOR-PORCH~CHIP ON BOTTOM STEP FRONT PORCH STEPS		<u>Christine Huyhn - Work: (647) 409-0713</u> <u>Ali Erol - Cell: (647) 408-1585</u>	NoAppoint.	55
12Aug22	21A ✓	1	Caledon Club	PDI 149383	Exterior-NOTE:-CHIP AT FIRST STEP		<u>Gaurav V. Patel - Home: (647) 401-8200</u> <u>Gayatriben R. Patel - Cell: (647) 627-6790</u>	NoAppoint.	26
27Jul22	22A ✓	1	Caledon Club	PDI 149120	EXTERIOR-PORCH~CHIP ON FIRST TREAD		<u>Gloria E Holder - Cell: (647) 401-0796</u> <u>Sherville Holder - (289) 242-2921</u>	NoAppoint.	42
14Jul22	10 ✓	1	Reserve Of Country Trails	30-Day 148866	Exterior- item 26- outdoor entrance stairs damage		<u>2ND H.O RANDEEP BASSI - Home: (647) 774-7777</u> <u>- Cell: (647) 774-7777</u>	02Aug22	55

Caledon Club - Mayfield Rd + McLaughlin Rd
Brampton.

Reserve of Country Trails - Mountainash Rd + CountrySide Drive.

Sept 9th - patched chips
bottom riser
(site damage)

Lot 21A
22A
8A

10
(May have a porch problem)

[Signature]

6 Rainbrook close.