50 July 11/22.

From:

Service - Medi Group

To: Subject: "Service Orders (Incoming Only)"
FW: Zancor Homes - Brampton

Date:

May 25, 2022 2:05:00 PM

From: Beata Slipska <Beata@zancorhomes.com>

Sent: May 25, 2022 1:35 PM **To:** service@medigroup.net

Subject: Zancor Homes - Brampton

Good Afternoon,

I need to book in two service requests for my site.

It has come to my attention that Lot 11 (which is now an occupied home) needs the hood vent relocated higher for a chimney vent. I have our service department going in tomorrow to do the inside prep and to drill a pilot hole for you guys. I prefer not to smash out any bricks ourselves. Lot 5 – dryer vent was missed at the time of brick work, need this done as well. Can you please let me know how it works with your department and what your schedules look like. Thank you kindly.

Kind Regards,

Bea Slípska

(416) 566-5475

Zancor Homes Brampton



MEDI GROUP Service

WO Number :

W-082037

WO Date :

07-Jul-2022

Issued To: Lucas De Sousa

Builder: Zancor

ZAN13

Lot No: 11

Project: ZANCOR-COUNTRY TRAILS-BRAM5-21

Model: 36-2 (B)

Directions: Brampton

Intersection of Countryside Drive and

Mountainash Road

Address:

Contact:

Main Brick: Portland

Main Stone:

Accent Brick:

Accent Stone: Citadel Traditional Grey

INIT

Item Work Description

PO

Builder Ref #

RELOCATE HOOD VENT HIGHER FOR A CHIMNEY VENT. I HAVE OUR SERVICE DEPARTMENTGOING IN TOMORROW TO DO THE INSIDE PREP AND TO DRILL A PILOT HOLE FOR YOU GUYS. I PREFER NOT TO SMASH OUT ANY BRICKS **OURSELVES**

11MAY2522 S-064557

H bricks removed
H bricks replaced 9569
multiple pin holes repointed

Homeowner Signature

Special Notes:

COMPLETED JUL 1 1 2022

Site Super Signature

Date Completed