Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 103

20Apr23	20Apr23	20Apr23	20Apr23	20Apr23	20Apr23 20Apr23		20Apr23	<u>Date</u> <u>Reported</u>
PDI	PDI	PDI	PDI	PDI		PDI	PDI	Туре
∞	7	6	S	4	ω	2		Number
Laundry Room- General- leak at tub	Exterior- General- install vent at left side of house	Exterior- General- complete fascia at porch and install column	Exterior- General- brick repair at right side of house	Basement- General- replace damaged vac pipe furnace area	Basement- General- bsmt bath - require vanity	Main Bathroom- General- replace laminate at side splashes	Throughout- General- require mirrors at master/main/powder/bsmt	Deficiency Description
Nota Plumbing & Heating Inc. 156390	Weatherstripping Ltd 156389	Promark Aluminum LTD. 156388	<u>Uni-tri</u> 156387	Smart Tech Systems <u>LTD.</u> 156386	New Image Kitchens 156385	New Image Kitchens 156384	Metropolitan 156383	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Add <u>Appointment</u> Trade <u>Date</u>
	×	×	×	×	×	X	<	Item Completed
Xa								Initial

Homeowner
Signatur
0

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: ARC 38 2

400 - NEWIMAGE. MEZ-REMAIE SHAPI EITHER



The items listed below were released to the homeowner(s) of

Purchaser	The above items were received on this 26 day of	_N/A_ Other	_N/A_ Recycling and Green Bins	< Homeowner Manual (given at PDI)	House and Garage Door Keys	Lot # 103 Site
Purchaser	day of APPIL. 2023					Site/Phase:Shoreline Point