



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W22955

Pack Slip:6068

Service Date: Jun 21, 2024

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Mar 06, 2024
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Time:
Site Fax: Lot#: 8TH FLOOR Order: H801169-1
Phase: 823

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (H801169-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 8TH FLOOR
Lot #: 8TH FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT ***SITE TO ALLOW ACCESS***

SUITE 823 - DEFECTIVE SPANDREL GLASS PANEL IS INSTALLED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
126	NEWMAR ALUMINUM SHADOW BOX	WBCH8-WS	GLASS ONLY -	45 1/4 X 112	6MM CARD LOWE 272	1
4	PL016948	23	FIXED + GLASS STOPS	1/16	SURF2 9.5 MM SUPERSPCR BLK 6MM HS OPACI #3-2135 GREY VELVET	

PO #92672 (TRULITE GLASS &) ETA 05-03-2024 ** RECEIVED ON 05-03-2024

Address Labels

BCH-8F-24-8R

Complete

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: 21/06/24

Approved:

Time:

Service Signature:

Miguel

MIGUEL