



**Zancor Homes (Innisfil) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

## Work Order

**Closing Date:** 29Jun23  
**Address:** 1315 Stevens Road  
Innisfil  
**Location:** Belle Aire Shores - Phase: 3 - Lot: 89W  
**Today's Date:** 09Jul24  
**Contact(s):** Leslie Martins (NEW HO) - Cell: (647) 688-3400 - (lesliemartins@hotmail.com)  
**Email:** lesliemartins@hotmail.com

**Company:** Promark Aluminum LTD.  
**Attention:** Kamar Kuyumju - Cell: 416-576-0236  
**Telephone:** (905) 857-5692  
**Fax:** (905) 857-5961

### Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
177571	1 Year	Exterior- General- Ceiling aluminum not installed properly @SOFFIT AT FRONT PORCH			
177575	1 Year	Exterior- General- incomplete repair to downspout, exposed wood- OVERCUT AT HARDY BOARD			

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

Date Completed: Sept 14, 2024

### Trade &/or Service Tech.

Signature: Davor

Print Name: Davor

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

## Belle Aire Shores - Phase: 3 - Lot: 89W

177571 - 1 - #8-1 (1) - Ceiling aluminum not installed properly @SOFFIT AT FRONT PORCH



177575 - 1 - #12 (1) - incomplete repair to downspout, exposed wood- OVERCUT AT HARDY BOARD

