

A M A C O N

L I V E W E L L

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 302 <u>302 - 3515 Kariya</u>
Closing Date	0000
Date	24Nov08
Contact Name(s)	Pamela Aros
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	9 (05-) 848--282
From:	Warranty Services Department - Head Office

Please complete the following items:

Deficiency Number	Issue		Appointment Date/Time	Notes
105 ✓	LIVING/DINING ROOM-FLOORING-BASEBOARD refinish 3rd floor board firm door along west wall	Repair deficiency if not notify Customer Service and Com-Kote will be notified	✓	
106 ✓	LIVING/DINING ROOM-FLOORING: 1-BASEBOARD touch up paint		✓	
107 ✓	LIVING/DINING ROOM-WALLS-touch up paint 1 foot below light switch		✓	
108 ✓	LIVING/DINING ROOM-WALLS: 1-mark on drywall west wall 12 inches below ceiling		✓	
109 ✓	MASTER BEDROOM-WALLS-DRYWALL DENTED under electrical panel		✓	
113	MAIN BATHROOM- TUB-SCRATCHED EDGE back left side	If deficiency cannot be repaired, Lisi Mechanical will be responsible	Dec 11/08. ✓	
115 ✓	KITCHEN- WALLS-DRYWALL DENTED left of stove along countertop		✓	

Dec. 09/2008.
Bravo