

AMACON

LIVE WELL

Warranty Services**Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827


Location	Eve - Tower: 1 - Unit: 2201 2201 - 3515 Kariya
Closing Date	0000
Date	07Jan09
Contact Name(s)	Lynette James
Contact Telephone#	
Company:	Barwood Flooring
Attention:	
Telephone:	
Fax:	(416) 431-2393
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
6750	LIVING/DINING ROOM-FLOORING-several scratches on flooring see taped area			REMOVED SCUFF MARKS.
6751	LIVING/DINING ROOM-FLOORING: 1-3 boards from kitchen teacup 2 scratches			REPLACED SCRATCHED BOARDS (5 PCS)
6752	LIVING/DINING ROOM-FLOORING: 2-2 scratches by island - 2' from island see tape			TOUCH - UP
6753	LIVING/DINING ROOM-FLOORING: 3-10th board - right side scratched see tape			
6754	LIVING/DINING ROOM-FLOORING: 4-left side - 3 boards from fancoil scratched - see tape			
6755	LIVING/DINING ROOM-FLOORING: 5-2nd board from balcony entry scratched - see tape			
6756	LIVING/DINING ROOM-FLOORING: 6-right of balcony entry - in front of left window pane scratched - see tape			

Date Completed:

JAN/07/2009

Amacon Customer Care Signature:


https://apps.prospectin.com/amacon/_builder/AMAServiceCall.php3?var_Centre=Eve&var... 1/7/2009