

**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 2209</u> <u>2209 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>22Jan09</u>
<b>Contact Name(s)</b>	<u>Tony Visconti</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Barwood Flooring</u>
<b>Attention:</b>	
<b>Telephone:</b>	
<b>Fax:</b>	<u>(416) 431-2393</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

**Please complete the following items:**

Deficiency Number	Issue	Appointment Date/Time	Notes
7534 ✓	FOYER / ENTRY- FLOORING-entry to bathroom 5th boards in entry floors chipped see tape	✓	
7535 ✓	FOYER / ENTRY- FLOORING: 1-entry to mirror closet right side boards 1 and 4 chipped see tape	✓	
7536 ✓	LIVING/DINING ROOM- FLOORING-hardwood in front of pantry - floor scratched - see tape 3 spots	✓	
7537 ✓	LIVING/DINING ROOM- FLOORING: 1-hardwood 8 boards right of balcony door scratched see tape	✓	
7539 ✓	LIVING/DINING ROOM- FLOORING: 3-10th board from centre large wall by bedroom board nit cleaned - see tape	✓	
7559 ✓	MASTER BEDROOM- FLOORING-entry t-cap scratched -- see tape	✓	

Date Completed:

Jan 22 2009

Amacon Customer Care Signature:

