


Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827


Location	<u>Eve - Tower: 1 - Unit: 2701</u> <u>2701 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>02Feb09</u>
Contact Name(s)	<u>Nam Ma</u>
Contact Telephone#	
Company:	<u>Barwood Flooring</u>
Attention:	
Telephone:	
Fax:	<u>(416) 431-2393</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
8364	LIVING/DINING ROOM- FLOORING-left corner edge by kitchen island baseboard dented see tape	✓		
8365	LIVING/DINING ROOM- FLOORING: 1-quarter round right side by kitchen island paint to be removed - see tape	✓		
8381	MASTER BEDROOM- FLOORING: 1-baseboard rightside by closet entry touchup needed --see tape	✓		
8382	MASTER BEDROOM- CLOSET-leftside dented see tape	✓		

Date Completed:

FEBRUARY 2, 09 

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. **Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

[Back - Forms Menu](#)

ID# 8364/8365/8381/8382 Eve Ph 1 Lot 2701